

V60CC MODEL YEAR 2024
Candidate List Substances Table

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2023 week 17

Localisation	Partnames	Substance/s
Engine - [cooling system]	PUMP, TWO-WAY VALVE, VALVE, HOSE TEMP SENSOR, HOSE OUTLET, TWIN CLIP, WATER PUMP, COOLER, CONDENSER, SET, RADIATOR, CHARGE AIR COOLER, TEMPERATURE SENSOR, THREE-WAY VALVE, BRACKET, CLAMP BRACKET, HOSE, RETAINER, HEATER HOSE, PIPE, EL WATER PUMP, COMPLETE COOLER, PRESSURE SENSOR, HOSE MODULE, OUTLET HOSE, THERMOSTAT HOUSING, O-RING, NIPPLE, INLET PIPE, PLASTIC PIPE, COVER, SIX POINT SOCKET SCREW, MODULE WATER PUMP, BRACKET TEMP SENSOR, STRIKER PLATE	TBBA [79-94-7], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclopentasiloxane [541-02-6], Melamine [108-78-1], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Octamethylcyclotetrasiloxane [556-67-2], Lead(II,IV)-oxide [1314-41-6], C,C'-azodi(formamide) [123-77-3]
Electric Power Supply / Instruments - [automatic monitoring / control]	CONTROL UNIT, RAIN SENSOR, REMOTE KEY, SENSOR, SIREN	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead(II,IV)-oxide [1314-41-6], TBBA [79-94-7]
Electric Power Supply / Instruments - [vehicle control system]	HARDWARE, SWITCH PANEL, STALK MODULE, CONTROL UNIT DOOR, BUTTON, ECU, SWITCH, COMBI INSTRUMENT, CUT-OFF SWITCH, USB POWER OUTLET, CONTROL PANEL POWER SEAT, SWITCH DOOR, SWITCH WINDOW LIFT, SWITCH MODULE, SWITCH STEERING WHEEL	Lead [7439-92-1], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Boric acid [10043-35-3], TBBA [79-94-7], 4,4'-Isopropylidenediphenol [80-05-7], Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Body, Interior / Exterior - [lock / handle]	DOOR LOCK, LOCK, LOCK CYLINDER SET, OUTER HANDLE, KEY, WIRE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Hexahydromethylphthalic-anhydride [25550-51-0], Melamine [108-78-1], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1]
Wheel Suspension / Steering [steering gear / wheel / shaft / column]	STEERING WHEEL, STEERING WHEEL RIM, STEERING COLUMN LOCK, STEERING GEAR, STEERING WHEEL HARNESS, STEERING COLUMN	Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, LOUDSPEAKER, SPEAKER MIDRANGE, AUDIO MODULE, WOOFER, SUBWOOFER, CENTRE LOUDSPEAKER	Diboron-trioxide [1303-86-2], Lead [7439-92-1], N,N-Dimethylacetamide [127-19-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9]

Body, Interior / Exterior - [air conditioning]	CLIMATE UNIT, FUEL OPERATED HEATER, IONIZER, SUN SENSOR, SENSOR, PROTECTIVE CAP, VALVE, HUMIDITY SENSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, FAN, CONTROL UNIT, SOLENOID CLUTCH, PIPE ASSEMBLY, AC-COMPRESSOR, AIR CLEANER, AIR INLET, VALVE CAP, CONTROL VALVE, CHANNEL SENSOR, SENSOR INTERIOR, FUEL PUMP	TBBA [79-94-7], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Lead [7439-92-1], Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt(II) nitrate hexahydrate [10026-22-9], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Octamethylcyclotetrasiloxane [556-67-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, BOX, RADAR	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6]
Engine - [fan]	FAN	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, REAR SCREEN, GLASS HARDENED	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [lighting]	OVERHEAD CONSOLE LENS, CONTROL UNIT HCM, HEADLAMP, READING LAMP, LIGHTING, LAMP LED, REAR LAMP REAR DOOR, REAR LAMP, FOG LIGHT, LED MODULE	Lead [7439-92-1], TBBA [79-94-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Melamine [108-78-1], Dicyclohexyl-phthalate [84-61-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Octamethylcyclotetrasiloxane [556-67-2], Lead-titanium-trioxide [12060-00-3]
Power Transmission - [front axle / rear axle / drive shaft]	AOC, DRIVE SHAFT, FEEDER PUMP KIT, VIBRATION DAMPER, BRACKET, REAR AXLE, PUMP UNIT, FINAL DRIVE, BEARING ANCHORAGE, FLANGE SCREW	Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Melamine [108-78-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SWITCH, LOCK BUTTON, LOCK BUTTON LED, ARM REST, LAMP LED, SIDE PANEL	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], TBBA [79-94-7], N,N-Dimethylacetamide [127-19-5]
Body, Interior / Exterior - [seats]	HEAD RESTRAINT, UPHOLSTERY, SIDE BOLSTER, HARDBACK, UNDERCARRIAGE, ARM REST, ENGINE TILT, ENGINE, HEATING PAD SEAT, VENTILATION, LUMBAR SUPPORT, STS SENSOR, FRAMEWORK, MASSAGE UNIT, BACKREST FRAME, CABLE HARNESS, SIX POINT SOCKET SCREW, FRAME, FAN, LUMBAR SUPPORT 4-WAY, HEATER	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], TBBA [79-94-7], Melamine [108-78-1], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Glutaral [111-30-8], N,N-Dimethylacetamide [127-19-5]

Body, Interior / Exterior - [front fender]	SHIM	Lead [7439-92-1]
Engine - [control systems]	TEMP AND PRESSURE SENSOR, AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, PRESSURE SENSOR	Lead [7439-92-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Dicyclohexyl-phthalate [84-61-7]
Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR OUTER, REAR VIEW MIRROR, CAMERA, GLASS, MOTOR UNIT	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Dicyclohexyl-phthalate [84-61-7], Lead-monoxide [1317-36-8], 2-Methylimidazole [693-98-1], Cobalt-dinitrate [10141-05-6]
Body, Interior / Exterior - [interior equipment]	JALUSIE, ARM REST, EC REAR VIEW MIRROR, DAMPER, LIGHTING, HINGE, LED MODULE, CUP HOLDER	C,C'-azodi(formamide) [123-77-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [battery and mounting parts]	BMS, BATTERY, SWITCH, BATTERY 48V	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,3-Propanesultone [1120-71-4], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3]
Engine - [selective catalytic reduction]	CONTROL UNIT, SENSOR, PUMP MODULE, BRACKET, TANK, CONTROL MODULE	Lead [7439-92-1], Nonylphenol [25154-52-3], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2]
Electric Power Supply / Instruments - [cleaner]	WIPER ARM, REAR WIPER MOTOR, WASHER FLUID RESERVOIR, WIPER APPARATUS, WIPER ARM DS, WIPER ARM PS, PUMP, DUAL PUMP	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead titanium zirconium oxide [12626-81-2]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, BRACKET, GEAR LEVER KNOB, GEAR SHIFT CABLE, HOUSING	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]

Electric Power Supply / Instruments - [antenna]	BLUETOOTH ANTENNA, ANTENNA AMPLIFIER, MAM ANTENNA MODULE, ANTENNA	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, BRAKE PIPE REAR	Lead [7439-92-1]
Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Engine - [engine / engine mounting]	ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET	Lead [7439-92-1]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD LOCK, HOOD LOCK CONTROL, HOOD RELEASE CABLE, COVER	Lead [7439-92-1], Imidazolidine-2-thione [96-45-7]
Body, Interior / Exterior - [side door]	SIDE DOOR, CARRIER PLATE, WINDOW LIFT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Power Transmission - [gearbox]	TORQUE CONVERTER, AUTOMATIC GEARBOX, CONTROL UNIT, VALVE BODY, CABLE HARNESS, CONNECTOR, SERVO COVER, CONTROL SYSTEM, OIL PUMP	Lead [7439-92-1], Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Diboron-trioxide [1303-86-2], Nonylphenol [25154-52-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT, BOX	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methylimidazole [693-98-1], Melamine [108-78-1]

Electric Power Supply / Instruments - [cable system]	CABLE HARNESS, CABLE, CABLE HARNESS WEM, CABLE FLOOR, CABLE DUCT, FLANGE NUT, FUSE BOX, FUSE BOX ASSY, BRACKET, CABLE PAC, CABLE TELE, CABLE INFOTAINMENT, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Cobalt-dinitrate [10141-05-6], 1,6,7,8,9,14,15,16,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 4,4'-Isopropylidenediphenol [80-05-7]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, STARTER MOTOR ALTERNATOR, COOLANT PIPE, SENSOR, STARTER MOTOR, BRACKET	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Dicyclohexyl-phthalate [84-61-7], N,N-Dimethylacetamide [127-19-5]
Body, Interior / Exterior - [roof]	PANORAMA ROOF, GLASS PANEL, WELD SEALANT CURING, ADHESIVE ROOF HATCH, MOTOR	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, WIRELESS CHARGE SYSTEM, BATTERY, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [fuel / EVAP system]	FUEL PUMP MODULE, PURGE VALVE, LEAK DETECTION PUMP, PURGE VALVE ASSY, CANISTER, FUEL PRESSURE SENSOR, HOSE, FUEL FILTER, FUEL TANK, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, FUEL PUMP, DELIVERY PIPE, INJECTOR, INJECTION VALVE	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [exterior equipment]	SPOILER, ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Lead [7439-92-1], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [seat belt / other restraining systems]	HEIGHT ADJUSTMENT, BELT CATCH, BELT CATCH REAR, SEAT BELT, BELT	Lead [7439-92-1], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [miscellaneous]	ABSORBER, TRANSPORT PROTECTION, SEALANT REPAIR, SOUND INSULATION	Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [trunk lid / tailgate complete]	TAILGATE, SPINDLE DRIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]

Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	FRONT SIDE MEMBER, WHEEL HOUSING, ADHESIVE, TOP COVER, REINFORCEMENT, TOP COVER PANEL REAR, BATTERY BOX, FLOOR PANEL	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [infotainment system]	CONTROL UNIT, USB HUB, GRAPHIC HEAD UP DISPLAY, PRINTED CIRCUIT BOARD, DISPLAY, TV TUNER	Lead-monoxide [1317-36-8], Lead [7439-92-1], 4,4'-Isopropylidenediphenol [80-05-7], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Boric acid [10043-35-3], Lead titanium zirconium oxide [12626-81-2]
Wheel Suspension / Steering - [axle member / link arm / suspension]	LOWER LINK ARM, UPPER LINK ARM	Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Body, Interior / Exterior - [instrument / radio panel]	INSTRUMENT PANEL, LAMP LED, CONCEALING PANEL, HINGE PIN, GLOVE BOX	Lead [7439-92-1], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Brake - [wheel brake]	BRAKE CALIPER, AIR VENTING NIPPLE, EPB, HOUSING, BLEEDER VALVE, BRAKE LINING	Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Dicyclohexyl-phthalate [84-61-7]
Electric Power Supply / Instruments - [protection]	SENSOR FRONT, SENSOR REAR	Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [recovery / towing unit]	TRM, HARNESS, TOWING HOOK	Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Lead-monoxide [1317-36-8], TBBA [79-94-7]
Body, Interior / Exterior - [airbag]	CONTROL UNIT SRS, AIRBAG MODULE, INFLATABLE CURTAIN	Lead-monoxide [1317-36-8], Lead [7439-92-1], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9]
Body, Interior / Exterior - [instruction / information plates]	DECAL SRS, SIX POINT SOCKET SCREW	2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], 1-Methyl-2-pyrrolidone [872-50-4]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING, ADHESIVE, REINFORCEMENT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [rim]	KEY, WHEEL BOLT	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]

Body, Interior / Exterior - [hood cover]	ANTIFLUTTER, HOOD, HINGE RELEASER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Brake - [brake control]	SENSOR, PEDAL UNIT	Lead [7439-92-1]
Electric Power Supply / Instruments - [alternator]	REGULATOR LIN, ALTERNATOR 210A	Lead [7439-92-1]
Engine - [intercooler / connection]	CHARGE AIR PIPE, CHARGE AIR COOLER	Lead [7439-92-1]
Electric Power Supply / Instruments - [starting system]	STARTER MOTOR	Lead [7439-92-1], Ethylenediamine [107-15-3], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [cable components]	RECEPTACLE HOUSING, CABLE DUCT	Lead [7439-92-1]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	ATTACHMENT, CEM	Lead [7439-92-1]
Engine - [emission equipment]	STAY, PRESSURE SENSOR, VALVE, COOLER, TEMPERATURE SENSOR EGT, TEMPERATURE SENSOR	Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Brake - [master cylinder / brake booster]	SHELL, BRAKE FLUID RESERVOIR, ACTUATION UNIT, MASTER CYLINDER	Lead [7439-92-1], TBBA [79-94-7]
Brake - [vacuum pump / tank / line / valve]	VACUUM HOSE	C,C'-azodi(formamide) [123-77-3]
Power Transmission - [final drive]	BRACKET, PT-UNIT	Lead [7439-92-1]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8]
Engine - [miscellaneous / help device installation]	SPLASH PROTECTION, BRACKET, TENSIONER, GUIDE SLEEVE	Lead [7439-92-1]
Body, Interior / Exterior - [tank hatch]	PLASTIC MODULE	Lead [7439-92-1]
Body, Interior / Exterior - [protective shields / flaps]	HEAT SHIELD PLATE	C,C'-azodi(formamide) [123-77-3]

Engine - [air cleaner]	BOX, RESONATOR, HOSE MODULE	Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system high voltage]	CHARGE CABLE CORD	Lead [7439-92-1], Melamine [108-78-1], Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Electric Power Supply / Instruments - [horn]	HORN	Lead [7439-92-1]
Engine - [supercharging]	SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, O-RING, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, MP TURBO, INLET PIPE	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Dicyclohexyl-phthalate [84-61-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-monoxide [1317-36-8]
Engine - [transmission]	TENSIONER, CAMSHAFT, IDLER PULLEY, BALANCE SHAFT, SOLENOID, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE	Lead [7439-92-1]
Engine - [lubricating and oil system]	OIL SUMP, SUCTION LINE, OIL PUMP, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, PISTON COOLING JET, OIL FILTER, PLUG, OIL PRESSURE SENSOR	Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Engine - [cylinder block / head]	CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [distributor]	CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]
Engine - [ignition / spark plug]	GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]