

**V90 MODEL YEAR 2024**  
**Candidate List Substances Table**

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2023 week 17

Localisation	Partnames	Substance/s
Engine - [cooling system]	PUMP, HEATER HOSE, TWO-WAY VALVE, VALVE, HOSE TEMP SENSOR, HOSE OUTLET, HOSE MODULE, TWIN CLIP, WATER PUMP, COOLER, CONDENSER, SET, RADIATOR HYBRID, TEMPERATURE SENSOR, RADIATOR, CHARGE AIR COOLER, SEPARATOR, BRACKET, HOSE, THREE-WAY VALVE, CLAMP BRACKET, RETAINER, PIPE, EL WATER PUMP, COMPLETE COOLER, PRESSURE SENSOR, HOSE HEATER, HOSE INLET, OUTLET HOSE, THERMOSTAT HOUSING, O-RING, NIPPLE, INLET PIPE, PLASTIC PIPE, COVER, SIX POINT SOCKET SCREW, MODULE WATER PUMP, BRACKET TEMP SENSOR, STRIKER PLATE	TBBA [79-94-7], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclopentasiloxane [541-02-6], Melamine [108-78-1], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Octamethylcyclotetrasiloxane [556-67-2], Lead(II,IV)-oxide [1314-41-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [air conditioning]	EL COMPRESSOR, CLIMATE UNIT, PIPE ASSEMBLY, FUEL OPERATED HEATER, SUN SENSOR, SENSOR, ELECTRIC HEATER, PROTECTIVE CAP, VALVE, HUMIDITY SENSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, FAN, EXPANSION VALVE, CHILLER, CONTROL UNIT, FLANGE SCREW, AIR CLEANER, AIR INLET, VALVE CAP, CHANNEL SENSOR, CONTROL VALVE, MAGNET CLUTCH, AC-COMPRESSOR, SENSOR INTERIOR, FUEL PUMP	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt-dichloride [7646-79-9], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], Octamethylcyclotetrasiloxane [556-67-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
Electric Power Supply / Instruments - [automatic monitoring / control]	CONTROL UNIT, SIREN, RAIN SENSOR, REMOTE KEY, SENSOR	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead(II,IV)-oxide [1314-41-6], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7]
Body, Interior / Exterior - [lock / handle]	DOOR LOCK, LOCK WITH ANTI THEFT COVE, LOCK, OUTER HANDLE, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, HANDLE, LOCK CYLINDER	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Hexahydromethylphthalic-anhydride [25550-51-0], Melamine [108-78-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
Frame / Springs / Damping / Wheels - [shock absorber]	SHOCK ABSORBER FRONT, SHOCK ABSORBER REAR, SHOCK ABSORBER	Lead [7439-92-1]

Wheel Suspension / Steering [steering gear / wheel / shaft / column]	STEERING WHEEL, STEERING WHEEL RIM, STEERING COLUMN LOCK, STEERING GEAR, STEERING COLUMN, STEERING WHEEL HARNESS	Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, SPEAKER MIDRANGE, AUDIO MODULE, SOUND MODULE, BRACKET, SUBWOOFER, WOOFER, LOUDSPEAKER, CENTRE LOUDSPEAKER	Diboron-trioxide [1303-86-2], Lead [7439-92-1], N,N-Dimethylacetamide [127-19-5], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Cobalt(II) nitrate hexahydrate [10026-22-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Engine - [fan]	FAN, FAN LOW	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16.9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [seats]	FRAMEWORK, UPHOLSTERY, HEAD RESTRAINT, HARDBACK, UNDERCARRIAGE, ARM REST, ENGINE TILT, ENGINE, HEATING PAD SEAT, VENTILATION, LUMBAR SUPPORT, STS SENSOR, MASSAGE UNIT, BACKREST FRAME, SIDE BOLSTER, HEATER, CABLE HARNESS, SIX POINT SOCKET SCREW, FRAME, FAN, LUMBAR SUPPORT 4-WAY	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], TBBA [79-94-7], Melamine [108-78-1], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Glutaral [111-30-8]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SILL MOULDING, WAISTRAIL, LIGHTING, LAMP LED, SILL FRONT, RUBBER MAT, GUIDE RAIL, SIDE PANEL, FLOOR HATCH, PANEL, TRUNK FLOOR SUPPORT, HEADLINING, BELT GUIDE, FLOOR CARPET	C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1], TBBA [79-94-7], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], Melamine [108-78-1], Paraffin oils, chloro [85422-92-0]
Body, Interior / Exterior - [interior equipment]	PADDING, ARM REST, FRAMEWORK, CARRIER, JALUSIE, CUP HOLDER, EC REAR VIEW MIRROR, COURTESY HANDLE, DAMPER, HINGE, SIDE PANEL, LIGHTING, RUBBER MAT, LED MODULE, CARRIER ARM REST	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], Cobalt-dinitrate [10141-05-6], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Power Transmission - [front axle / rear axle / drive shaft]	AOC, PUMP UNIT, CABLE HARNESS, DRIVE SHAFT, REAR AXLE, BEARING ANCHORAGE, VIBRATION DAMPER, BRACKET, FINAL DRIVE, FLANGE SCREW	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Cobalt-dichloride [7646-79-9]
Engine - [air cleaner]	FRESH AIR PIPE, BOX, RESONATOR, HOSE MODULE	Lead [7439-92-1]

Engine - [fuel / EVAP system]	PURGE VALVE ASSY, FUEL PUMP MODULE, PUMP MODULE, JET PUMP AND LEVEL SENSOR, PURGE VALVE, ISOLATION VALVE, LEAK DETECTION PUMP, CANISTER, FUEL PRESSURE SENSOR, HOSE, FUEL FILTER, FUEL TANK, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, FUEL PUMP, DELIVERY PIPE, INJECTOR, INJECTION VALVE	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dinitrate [10141-05-6], C,C'-azodi(formamide) [123-77-3]
Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, TAILPIPE, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Electric Power Supply / Instruments - [vehicle control system]	SWITCH PANEL, CONTROL UNIT DOOR, BUTTON, ECU, STALK MODULE, SWITCH, HARDWARE, LOCK BUTTON, LOCK BUTTON LED, COMBI INSTRUMENT, CUT-OFF SWITCH, USB POWER OUTLET, SWITCH WINDOW LIFT, GEAR SHIFT PADDLE, CONTROL PANEL POWER SEAT, SWITCH DOOR, SWITCH MODULE, SWITCH STEERING WHEEL	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Boric acid [10043-35-3], 4,4'-Isopropylidenediphenol [80-05-7]
Electric Power Supply / Instruments - [infotainment system]	DISPLAY, GRAPHIC HEAD UP DISPLAY, CONTROL UNIT, USB HUB, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-titanium-trioxide [12060-00-3], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], TBBA [79-94-7], Melamine [108-78-1], Boric acid [10043-35-3], Silicic acid, lead salt [11120-22-2]
Body, Interior / Exterior - [front fender]	SHIM, FRONT FENDER	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [control systems]	TEMP AND PRESSURE SENSOR, AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, PRESSURE SENSOR	Lead [7439-92-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Dicyclohexyl-phthalate [84-61-7], Lead titanium zirconium oxide [12626-81-2]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, RADAR	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6]
Electric Power Supply / Instruments - [cable system high voltage]	STRAIN RELIEF, CABLE HARNESS, CABLE CHARGE POINT HV, BRACKET, CABLE DUCT, CHARGE CABLE CORD, CABLE CHANNEL, CHARGE CABLE	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Octamethylcyclotetrasiloxane [556-67-2], Melamine [108-78-1]

Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [battery and mounting parts]	BMS, CURRENT SENSOR, BATTERY, FILTER BOARD ASSY, MODULE, SWITCH, CONTROL UNIT, BATTERY 48V, COVER, HEAT INSULATION PAD, SERVICE SWITCH, INLET HOSE, OUTLET HOSE, FILTER BOARD, HEAT SHIELD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,3-Propanesultone [1120-71-4], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Melamine [108-78-1], Boric acid [10043-35-3], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [lighting]	CONTROL UNIT HCM, HEADLAMP, OVERHEAD CONSOLE LENS, READING LAMP, LIGHTING, LIGHTNING INSTRUMENT PANEL, LED MODULE, STOP LAMP, LAMP LED, REAR LAMP, FOG LIGHT	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 1-Methyl-2-pyrrolidone [872-50-4], Dicyclohexyl-phthalate [84-61-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3]
Engine - [selective catalytic reduction]	CONTROL UNIT, SENSOR, PUMP MODULE, BRACKET, TANK, CONTROL MODULE	Lead [7439-92-1], Nonylphenol [25154-52-3], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2]
Body, Interior / Exterior - [tank hatch]	ACTUATOR, PLASTIC MODULE	Lead [7439-92-1], TBBA [79-94-7]
Power Transmission - [electrical axis drive]	CABLE HARNESS, REAR AXLE, SERVICE KIT, TWIN DISC CLUTCH, TRANSMISSION HOUSE, PLANET CARRIER, PLUG	Lead [7439-92-1], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Electric Power Supply / Instruments - [cable system]	CABLE, CABLE HARNESS, CABLE FLOOR, CABLE HARNESS WEM, CABLE DUCT, BRACKET, FUSE BOX, EJB, FLANGE NUT, DISCONNECTOR POWER, FUSE BOX ASSY, CABLE PAC, PRINTED CIRCUIT BOARD, CABLE INFOTAINMENT	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], Dicyclohexyl-phthalate [84-61-7], Cobalt-dinitrate [10141-05-6], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 4,4'-Isopropylidenediphenol [80-05-7]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, INSERT, ACTUATOR	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, BRAKE PIPE REAR	Lead [7439-92-1]

Engine - [engine / engine mounting]	ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET, FRONT AXLE, ELECTRIC MOTOR, REAR AXLE, INNER HOUSING, OUTER HOUSING, BRACKET, O-RING, STRAIN RELIEF, CABLE HARNESS	Lead [7439-92-1], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], Decamethylcyclotetrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD LOCK, COVER, FOAM, HOOD RELEASE CABLE, HOOD LOCK CONTROL	Lead [7439-92-1], C,C'-azodi(formamide) [123-77-3], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Imidazolidine-2-thione [96-45-7]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Power Transmission - [gearbox]	TORQUE CONVERTER, AUTOMATIC GEARBOX, CONTROL UNIT, VALVE BODY, CABLE HARNESS, CONNECTOR, SERVO COVER, CONTROL SYSTEM, OIL PUMP, ADAPTER, FLANGE NUT, DIFFERENTIAL SPACER, LID, FLANGE SCREW	Lead [7439-92-1], Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Diboron-trioxide [1303-86-2], Nonylphenol [25154-52-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Cobalt-dinitrate [10141-05-6], Cobalt-dichloride [7646-79-9], Lead-titanium-trioxide [12060-00-3], Silicic acid, lead salt [11120-22-2]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, GLASS HARDENED, GLASS LAMINATED, REAR SCREEN, QUARTER GLASS HARDENED, QUARTER GLASS LAMINATED	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR, CAMERA, REAR VIEW MIRROR OUTER, GLASS, MOTOR UNIT	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Dicyclohexyl-phthalate [84-61-7], Lead-monoxide [1317-36-8], 2-Methylimidazole [693-98-1], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6]
Body, Interior / Exterior - [side door]	SIDE DOOR, WINDOW LIFT, HEMMING ADHESIVE, CARRIER PLATE, BODY MOUNTED SEALING, DOOR MOUNTED SEALING	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], Imidazolidine-2-thione [96-45-7], C,C'-azodi(formamide) [123-77-3]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1]

Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, INVERTER IEM, STARTER MOTOR ALTERNATOR, ONBOARD CHARGER, PROTECTION HIGH VOLTAGE, BRACKET, INVERTER IGM, COOLANT PIPE, SENSOR, STARTER MOTOR, FLANGE SCREW	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Dicyclohexyl-phthalate [84-61-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Alkanes, C14-17, chloro [85535-85-9], N,N-Dimethylacetamide [127-19-5], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [roof]	PANORAMA ROOF, GLASS PANEL, WELD SEALANT CURING, ADHESIVE ROOF HATCH, MOTOR	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, WIRELESS CHARGE SYSTEM, BATTERY, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [seat belt / other restraining systems]	HEIGHT ADJUSTMENT, BELT CATCH, SEAT BELT, LOAD NET, BELT CATCH REAR, BELT	Lead [7439-92-1], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [cleaner]	WIPER UNIT, WASHER FLUID RESERVOIR, REAR WIPER, HEADLAMP WIPER, PUMP, DUAL PUMP, WIPER ARM	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Wheel Suspension / Steering - [axle member / link arm / suspension]	LOWER LINK ARM, SUBFRAME FRONT, UPPER LINK ARM, BALL JOINT	Imidazolidine-2-thione [96-45-7], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	BUMPER BEAM, FRONT SIDE MEMBER, WHEEL HOUSING, WELD SEALANT CURING, ADHESIVE, TOP COVER, REINFORCEMENT, SIDE MEMBER UPPER INNER, BRACE INNER, BRACE OUTER, CRASH BOX REINFORCEMENT, FLOOR PANEL, BATTERY TRAY, CRASH BOX	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [emission equipment]	COOLER, STAY, PRESSURE SENSOR, VALVE, ALUMINIUM, TEMPERATURE SENSOR EGT, TEMPERATURE SENSOR	Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2]
Engine - [intercooler / connection]	CHARGE AIR COOLER, CHARGE AIR HOSE, CHARGE AIR PIPE, RESONATOR	Lead [7439-92-1], Boric acid [10043-35-3]

Body, Interior / Exterior - [trunk lid / tailgate complete]	REAR DOOR, SPINDLE DRIVE	Lead [7439-92-1], TBBA [79-94-7], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8]
Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, TRM, HARNESS	Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Lead-monoxide [1317-36-8], TBBA [79-94-7]
Brake - [wheel brake]	BRAKE CALIPER, AIR VENTING NIPPLE, EPB, BRAKE LINING, BLEEDER VALVE, HOUSING	Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Dicyclohexyl-phthalate [84-61-7]
Electric Power Supply / Instruments - [protection]	SENSOR REAR, SENSOR FRONT, CONTROL UNIT, ACCELEROMETER, ACCELEROMETER FRONT	Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [airbag]	AIRBAG MODULE, ACCELEROMETER SENSOR, CONTROL UNIT	4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead [7439-92-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING, ADHESIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Frame / Springs / Damping / Wheels - [rim]	KEY, WHEEL BOLT, WHEEL, ADHESIVE BALANCE WEIGHT	Lead [7439-92-1], 2-Ethoxyethyl acetate [111-15-9], Diboron-trioxide [1303-86-2]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION, SEALANT REPAIR, SEALING, SOUND INSULATION	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2]
Brake - [brake control]	SENSOR, PEDAL UNIT	Lead [7439-92-1]
Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, ANTENNA	TBBA [79-94-7], Lead [7439-92-1], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Body, Interior / Exterior - [instrument / radio panel]	STORAGE BOX, HINGE PIN, LAMP LED, CONCEALING PANEL, GLOVE BOX	Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [instruction / information plates]	DECAL SRS, SIX POINT SOCKET SCREW	2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], 1-Methyl-2-pyrrolidone [872-50-4]

Electric Power Supply / Instruments - [electrical distribution box / fuse box]	ATTACHMENT, CEM	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	RESEVOIR, HOSE COUPLING, VALVE BLOCK, AIR SPRING REAR, COMPRESSOR	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Tris(nonylphenyl)phosphite [26523-78-4]
Electric Power Supply / Instruments - [horn]	HORN	Lead [7439-92-1]
Body, Interior / Exterior - [exterior equipment]	ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [starting system]	STARTER MOTOR	Lead [7439-92-1]
Body, Interior / Exterior - [tool / jack]	JACK	Ethylenediamine [107-15-3]
Power Transmission - [actuator, gear shift]	CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Silicic acid, lead salt [11120-22-2]
Body, Interior / Exterior - [hood cover]	FOAM, HOOD	C,C'-azodi(formamide) [123-77-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8]
Engine - [miscellaneous / help device installation]	SPLASH PROTECTION, BRACKET, TENSIONER, GUIDE SLEEVE	Lead [7439-92-1]
Power Transmission - [final drive]	BRACKET, PT-UNIT	Lead [7439-92-1]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Engine - [supercharging]	SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, O-RING, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, MP TURBO, INLET PIPE	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Dicyclohexyl-phthalate [84-61-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-monoxide [1317-36-8]



Engine - [transmission]	TENSIONER, CAMSHAFT, IDLER PULLEY, BALANCE SHAFT, SOLENOID, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE	Lead [7439-92-1]
Engine - [lubricating and oil system]	OIL SUMP, SUCTION LINE, OIL PUMP, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, PISTON COOLING JET, OIL FILTER, PLUG, OIL PRESSURE SENSOR	Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Engine - [cylinder block / head]	CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [distributor]	CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]
Engine - [ignition / spark plug]	GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]