

XC60 MODEL YEAR 2024
Candidate List Substances Table

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2023 week 17

Localisation	Partnames	Substance/s
Body, Interior / Exterior - [interior equipment]	JALUSIE, ARM REST, CUP HOLDER, EC REAR VIEW MIRROR, DAMPER, LIGHTING, HINGE, LED MODULE	C,C'-azodi(formamide) [123-77-3], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7]
Engine - [cooling system]	PUMP, HOSE COLD ZONE, TWO-WAY VALVE, VALVE, HOSE TEMP SENSOR, HOSE OUTLET, HOSE MODULE, TWIN CLIP, WATER PUMP, COOLER, CONDENSER, SET, RADIATOR HYBRID, TEMPERATURE SENSOR, RADIATOR, CHARGE AIR COOLER, SEPARATOR, BRACKET, HOSE, THREE-WAY VALVE, CLAMP BRACKET, RETAINER, HEATER HOSE, PIPE, EL WATER PUMP, COMPLETE COOLER, PRESSURE SENSOR, HOSE HEATER, HOSE INLET, OUTLET HOSE, THERMOSTAT HOUSING, O-RING, NIPPLE, INLET PIPE, PLASTIC PIPE, COVER, SIX POINT SOCKET SCREW, MODULE WATER PUMP, BRACKET TEMP SENSOR, STRIKER PLATE	TBBA [79-94-7], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclopentasiloxane [541-02-6], Melamine [108-78-1], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Octamethylcyclotetrasiloxane [556-67-2], Lead(II,IV)-oxide [1314-41-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [air conditioning]	EL COMPRESSOR, CLIMATE UNIT, PIPE ASSEMBLY, FUEL OPERATED HEATER, IONIZER, SUN SENSOR, SENSOR, ELECTRIC HEATER, PROTECTIVE CAP, HUMIDITY SENSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, FAN, EXPANSION VALVE, CHILLER, CONTROL UNIT, SOLENOID CLUTCH, AC-COMPRESSOR, FLANGE SCREW, AIR CLEANER, AIR INLET, VALVE, VALVE CAP, CONTROL VALVE, CHANNEL SENSOR, SENSOR INTERIOR, FUEL PUMP	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dichloride [7646-79-9], Melamine [108-78-1], Octamethylcyclotetrasiloxane [556-67-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
Body, Interior / Exterior - [front fender]	SENSOR, SHIM, ANTIFLUTTER, FRONT FENDER	Lead-monoxide [1317-36-8], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, BOX, RADAR	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6]

Frame / Springs / Damping / Wheels - [shock absorber]	SHOCK ABSORBER FRONT, SHOCK ABSORBER, SHOCK ABSORBER REAR, TOPMOUNT	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [lock / handle]	DOOR LOCK, LOCK WITH ANTI THEFT COVE, LOCK, OUTER HANDLE, CAMERA, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, HANDLE, LOCK CYLINDER, WIRE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dicyclohexyl-phthalate [84-61-7], 2-Methylimidazole [693-98-1], Lead titanium zirconium oxide [12626-81-2], Hexahydromethylphthalic-anhydride [25550-51-0], Melamine [108-78-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1]
Electric Power Supply / Instruments - [battery and mounting parts]	BATTERY, BMS, CURRENT SENSOR, FILTER BOARD ASSY, MODULE, SWITCH, CONTROL UNIT, COVER, HEAT INSULATION PAD, SERVICE SWITCH, INLET HOSE, OUTLET HOSE, FILTER BOARD, HEAT SHIELD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,3-Propanesultone [1120-71-4], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Melamine [108-78-1], Boric acid [10043-35-3]
Wheel Suspension / Steering [steering gear / wheel / shaft / column]	STEERING WHEEL, STEERING WHEEL RIM, STEERING COLUMN LOCK, STEERING COLUMN, STEERING GEAR, STEERING WHEEL HARNESS	Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SIDE PANEL, RUBBER MAT, LAMP LED, LUGGAGE COVER	C,C'-azodi(formamide) [123-77-3], TBBA [79-94-7], N,N-Dimethylacetamide [127-19-5], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, LOUDSPEAKER, SPEAKER MIDRANGE, AUDIO MODULE, SOUND MODULE, BRACKET, WOOFER, SUBWOOFER, CENTRE LOUDSPEAKER	Diboron-trioxide [1303-86-2], Lead [7439-92-1], N,N-Dimethylacetamide [127-19-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9]
Engine - [fan]	FAN, FAN LOW	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [seats]	FRAMEWORK, HEAD RESTRAINT, UPHOLSTERY, HARDBACK, UNDERCARRIAGE, ARM REST, ENGINE TILT, ENGINE, HEATING PAD SEAT, VENTILATION, LUMBAR SUPPORT, STS SENSOR, MASSAGE UNIT, BACKREST FRAME, VINYL, CUP HOLDER, HEATER, CABLE HARNESS, SIX POINT SOCKET SCREW, FRAME, FAN, LUMBAR SUPPORT 4-WAY, SIDE BOLSTER, HARNESS	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Glutaral [111-30-8], N,N-Dimethylacetamide [127-19-5], TBBA [79-94-7], Melamine [108-78-1], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3]

Power Transmission - [electrical axis drive]	DRIVE SHAFT, CABLE HARNESS, REAR AXLE, SERVICE KIT, TWIN DISC CLUTCH, TRANSMISSION HOUSE, PLANET CARRIER, PLUG	Lead [7439-92-1], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Power Transmission - [front axle / rear axle / drive shaft]	DRIVE SHAFT, AOC, PUMP UNIT, CABLE HARNESS, REAR AXLE, FEEDER PUMP KIT, VIBRATION DAMPER, BRACKET, FINAL DRIVE, BEARING ANCHORAGE, FLANGE SCREW	Lead [7439-92-1], Decamethylcyclotetrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Melamine [108-78-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Cobalt-dichloride [7646-79-9]
Engine - [air cleaner]	FRESH AIR PIPE, BOX, RESONATOR, HOSE MODULE	Lead [7439-92-1]
Engine - [fuel / EVAP system]	PURGE VALVE ASSY, FUEL PUMP MODULE, PUMP MODULE, JET PUMP AND LEVEL SENSOR, EVAP PURGE PUMP, PURGE VALVE, LEAK DETECTION PUMP, ISOLATION VALVE, CANISTER, FUEL PRESSURE SENSOR, HOSE, FUEL FILTER, FUEL TANK, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, FUEL PUMP, DELIVERY PIPE, INJECTOR, INJECTION VALVE	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dinitrate [10141-05-6]
Brake - [wheel brake]	BRAKE CALIPER, AIR VENTING NIPPLE, EPB, HOUSING, BLEEDER VALVE, BRAKE LINING	Decamethylcyclotetrasiloxane [541-02-6], Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Dicyclohexyl-phthalate [84-61-7]
Electric Power Supply / Instruments - [vehicle control system]	SWITCH PANEL, STALK MODULE, CONTROL UNIT DOOR, LOCK BUTTON, SWITCH, BUTTON, ECU, HARDWARE, LOCK BUTTON LED, COMBI INSTRUMENT, CUT-OFF SWITCH, USB POWER OUTLET, GEAR SHIFT PADDLE, CONTROL PANEL POWER SEAT, SWITCH DOOR, SWITCH WINDOW LIFT, SWITCH MODULE, SWITCH STEERING WHEEL	Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Boric acid [10043-35-3], 4,4'-Isopropylidenediphenol [80-05-7]
Engine - [control systems]	TEMP AND PRESSURE SENSOR, AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, PRESSURE SENSOR	Lead [7439-92-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Dicyclohexyl-phthalate [84-61-7], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [cable system high voltage]	STRAIN RELIEF, CABLE CHARGE POINT HV, CABLE HARNESS, BRACKET, CABLE DUCT, CHARGE CABLE CORD, CABLE CHANNEL, CHARGE CABLE	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Octamethylcyclotetrasiloxane [556-67-2], Melamine [108-78-1]
Electric Power Supply / Instruments - [cable components]	STRAIN RELIEF, FUSE BOX, CABLE DUCT, RECEPTACLE HOUSING, UNLOADING CABLE, PRINTED CIRCUIT BOARD, EJB, DISCONNECTOR POWER, CABLE, CABLE CHANNEL, BATTERY TERMINAL, FUSE BOX ASSY, SPLICE, FUSE BOX REAR, RETAINER, CHANNEL, AIR HOSE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Octamethylcyclotetrasiloxane [556-67-2]

Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [lighting]	CONTROL UNIT HCM, REAR LAMP, HEADLAMP, OVERHEAD CONSOLE LENS, READING LAMP, FOG LIGHT, LIGHTING, STOP LAMP, LAMP LED, LED MODULE	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Octamethylcyclotetrasiloxane [556-67-2], Dicyclohexyl-phthalate [84-61-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9]
Electric Power Supply / Instruments - [cleaner]	WIPER ARM AND BLADE DS, WIPER ARM AND BLADE PS, WIPER ARM AND BLADE, REAR WIPER MOTOR, WIPER APPARATUS, WASHER FLUID RESERVOIR, WIPER ARM DS, WIPER ARM PS, NOZZLE, PUMP, DUAL PUMP	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead titanium zirconium oxide [12626-81-2], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1]
Engine - [selective catalytic reduction]	CONTROL UNIT, SENSOR, PUMP MODULE, BRACKET, TANK, CONTROL MODULE	Lead [7439-92-1], Nonylphenol [25154-52-3], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2]
Electric Power Supply / Instruments - [cable system]	CABLE HARNESS, CABLE, CABLE FLOOR, CABLE HARNESS WEM, CABLE HARNESS BUMPER, CABLE HARNESS TAILGATE, FUSE BOX, CABLE DUCT, EJB, FLANGE NUT, FUSE BOX ASSY, PRINTED CIRCUIT BOARD, CABLE AUDIO, CABLE INTERIOR, CABLE LOCKING DEVICE, CABLE FRONT SEATS, CABLE PAC, CABLE INFOTAINMENT	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Cobalt-dinitrate [10141-05-6], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 4,4'-Isopropylidenediphenol [80-05-7]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, BRACKET, GEAR LEVER KNOB, INSERT, HOUSING, ACTUATOR	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], 4,4'-Isopropylidenediphenol [80-05-7], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7]
Body, Interior / Exterior - [glass, window / windscreen / roof]	QUARTER GLASS LAMINATED, REAR SCREEN, WINDSCREEN, GLASS HARDENED, GLASS LAMINATED, QUARTER GLASS HARDENED	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, BRAKE PIPE REAR, BRAKE HOSE	Lead [7439-92-1]
Engine - [engine / engine mounting]	ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET, FRONT AXLE, ELECTRIC MOTOR, REAR AXLE, INNER HOUSING, OUTER HOUSING, BRACKET, O-RING, STRAIN RELIEF, CABLE HARNESS	Lead [7439-92-1], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3]

Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	WHEEL HOUSING, FRONT SIDE MEMBER, ADHESIVE, TOP COVER, BRACE OUTER, BRACE, SIDE MEMBER, FLOOR PANEL, BACK PANEL, SIDE MEMBER UPPER INNER, BATTERY BOX	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD LOCK, COVER, HOOD RELEASE CABLE, FOAM, HOOD LOCK CONTROL	Lead [7439-92-1], Imidazolidine-2-thione [96-45-7], C,C'-azodi(formamide) [123-77-3]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Power Transmission - [gearbox]	TORQUE CONVERTER, AUTOMATIC GEARBOX, CONTROL UNIT, VALVE BODY, CABLE HARNESS, CONNECTOR, SERVO COVER, CONTROL SYSTEM, OIL PUMP, ADAPTER, FLANGE NUT, DIFFERENTIAL SPACER, LID, FLANGE SCREW	Lead [7439-92-1], Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Diboron-trioxide [1303-86-2], Nonylphenol [25154-52-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Cobalt-dinitrate [10141-05-6], Cobalt-dichloride [7646-79-9], Silicic acid, lead salt [11120-22-2]
Body, Interior / Exterior - [side door]	BODY MOUNTED SEALING, DOOR MOUNTED SEALING, SPLITLINE SEAL, WINDOW LIFT, CARRIER PLATE, SIDE DOOR, HEMMING ADHESIVE	C,C'-azodi(formamide) [123-77-3], Imidazolidine-2-thione [96-45-7], Dodecamethylcyclhexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, TRM, HARNESS	Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Lead-monoxide [1317-36-8], TBBA [79-94-7]
Electric Power Supply / Instruments - [automatic monitoring / control]	RAIN SENSOR, CONTROL UNIT, REMOTE KEY, SENSOR, SIREN	Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, TAILPIPE, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1]
Body, Interior / Exterior - [trunk lid / tailgate complete]	SPINDLE DRIVE, REAR DOOR	Lead [7439-92-1]

Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, INVERTER IEM, STARTER MOTOR ALTERNATOR, ONBOARD CHARGER, PROTECTION HIGH VOLTAGE, BRACKET, INVERTER IGM, COOLANT PIPE, SENSOR, STARTER MOTOR, FLANGE SCREW	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Dicyclohexyl-phthalate [84-61-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Alkanes, C14-17, chloro [85535-85-9], N,N-Dimethylacetamide [127-19-5], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [roof]	PANORAMA ROOF, GLASS PANEL, ROOF HATCH, ADHESIVE ROOF HATCH, ADHESIVE, MOTOR, SEALING, SEALING STRIP	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], C,C'-azodi(formamide) [123-77-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, WIRELESS CHARGE SYSTEM, ANTENNA, BATTERY, BACK-UP BATTERY, AUXILIARY TELEMATIC, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], N,N-Dimethylacetamide [127-19-5], Diocetyl tin dilaurate [3648-18-8]
Body, Interior / Exterior - [seat belt / other restraining systems]	HEIGHT ADJUSTMENT, BELT CATCH, BELT, SEAT BELT	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dinitrate [10141-05-6], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], TBBA [79-94-7]
Wheel Suspension / Steering - [axle member / link arm / suspension]	LOWER LINK ARM, SUBFRAME FRONT, UPPER LINK ARM	Imidazolidine-2-thione [96-45-7], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Engine - [emission equipment]	COOLER, STAY, PRESSURE SENSOR, VALVE, ALUMINIUM, TEMPERATURE SENSOR EGT, TEMPERATURE SENSOR	Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2]
Engine - [intercooler / connection]	CHARGE AIR COOLER, CHARGE AIR PIPE, CHARGE AIR HOSE, RESONATOR	Lead [7439-92-1], Boric acid [10043-35-3]
Electric Power Supply / Instruments - [infotainment system]	CONTROL UNIT, GRAPHIC HEAD UP DISPLAY, USB HUB, DISPLAY, PRINTED CIRCUIT BOARD	Lead-monoxide [1317-36-8], Lead [7439-92-1], 4,4'-Isopropylidenediphenol [80-05-7], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Boric acid [10043-35-3], Lead titanium zirconium oxide [12626-81-2]
Body, Interior / Exterior - [tank hatch]	PLASTIC MODULE	Lead [7439-92-1], TBBA [79-94-7]

Body, Interior / Exterior - [outside mirrors]	CAMERA, REAR VIEW MIRROR OUTER, REAR VIEW MIRROR, MOTOR UNIT, DIRECTION INDICATOR, TEMPERATURE SENSOR, GLASS, REAR VIEW MIRROR CASING	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Dicyclohexylphthalate [84-61-7], Octamethylcyclotetrasiloxane [556-67-2], 2-Methylimidazole [693-98-1], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Tris(nonylphenyl)phosphite [26523-78-4], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1]
Body, Interior / Exterior - [exterior equipment]	ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [hood cover]	HOOD, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [protection]	SENSOR FRONT, SENSOR REAR, CONTROL UNIT, ACCELEROMETER, ACCELEROMETER FRONT	Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [airbag]	AIRBAG MODULE, ACCELEROMETER SENSOR, CONTROL UNIT, INFLATABLE CURTAIN	4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead [7439-92-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3]
Body, Interior / Exterior - [instruction / information plates]	DECAL SRS, NUMBER PLATE HOLDER, SIX POINT SOCKET SCREW	2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], Imidazolidine-2-thione [96-45-7], 1-Methyl-2-pyrrolidone [872-50-4]
Frame / Springs / Damping / Wheels - [rim]	KEY, WHEEL BOLT, ADHESIVE BALANCE WEIGHT	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION, SEALANT REPAIR, SEALING, SOUND INSULATION	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2]
Brake - [brake control]	SENSOR, PEDAL UNIT	Lead [7439-92-1]
Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, ETC ON BOARD UNIT, ANTENNA, ETC MODULE	TBBA [79-94-7], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Electric Power Supply / Instruments - [alternator]	REGULATOR LIN, ALTERNATOR 210A	Lead [7439-92-1]

Electric Power Supply / Instruments - [starting system]	STARTER MOTOR	Lead [7439-92-1], Ethylenediamine [107-15-3]
Body, Interior / Exterior - [instrument / radio panel]	HINGE PIN, LAMP LED, ADAPTER BRACKET, GLOVE BOX, DASHBOARD, CONCEALING PANEL	Lead [7439-92-1], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	AIR HOSE BUNDLE, CONNECTOR, HOSE COUPLING, VALVE BLOCK, RESEVOIR, T-CONNECTION, AIR SPRING REAR, SHOCK ABSORBER FRONT, AIR SPRING FRONT, TOPMOUNT, COMPRESSOR	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Tris(nonylphenyl)phosphite [26523-78-4]
Body, Interior / Exterior - [bumper with mounting / damping]	NUMBER PLATE HOLDER	Imidazolidine-2-thione [96-45-7]
Engine - [miscellaneous / help device installation]	BRACKET, SPLASH PROTECTION, TENSIONER, GUIDE SLEEVE	Lead [7439-92-1]
Power Transmission - [final drive]	PT-UNIT, BRACKET	Lead [7439-92-1]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	ATTACHMENT, CEM	Lead [7439-92-1]
Electric Power Supply / Instruments - [horn]	HORN	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Brake - [vacuum pump / tank / line / valve]	VACUUM HOSE	C,C'-azodi(formamide) [123-77-3]
Power Transmission - [actuator, gear shift]	CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Silicic acid, lead salt [11120-22-2]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Body, Interior / Exterior - [outside / exterior trim]	GRILLE	C,C'-azodi(formamide) [123-77-3]

Engine - [supercharging]	SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, O-RING, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, MP TURBO, INLET PIPE	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Dicyclohexyl-phthalate [84-61-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-monoxide [1317-36-8]
Engine - [transmission]	TENSIONER, CAMSHAFT, IDLER PULLEY, BALANCE SHAFT, SOLENOID, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE	Lead [7439-92-1]
Engine - [lubricating and oil system]	OIL SUMP, SUCTION LINE, OIL PUMP, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, PISTON COOLING JET, OIL FILTER, PLUG, OIL PRESSURE SENSOR	Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Engine - [cylinder block / head]	CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [distributor]	CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]
Engine - [ignition / spark plug]	GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]