

**C40 MODEL YEAR 2024  
Candidate List Substances Table**

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2023 week 41.

Localisation	Partnames	Substance/s
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, RADAR, EXT743	Lead-monoxide [1317-36-8], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9]
Electric Power Supply / Instruments - [cable components]	CHANNEL, FUSE BOX HOUSING, FRAME ASSY, BRACKET, STRAIN RELIEF, CABLE DUCT, RECEPTACLE HOUSING, DISCONNECTOR POWER, DIODE, FUSE BOX, BOTTOM PART, ADAPTER PLATE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [cleaner]	WASHER FLUID RESERVOIR, PUMP, WIPER APPARATUS, WIPER ARM, WASHER PUMP	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Imidazolidine-2-thione [96-45-7]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SHIM, REAR SHELF	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Body, Interior / Exterior - [lock / handle]	DOOR LOCK, LOCK, OUTER HANDLE, LOCK CYLINDER SET, EXT743, KEY	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Hexahydromethylphthalic-anhydride [25550-51-0], Melamine [108-78-1]
Body, Interior / Exterior - [side door]	CARRIER	Lead [7439-92-1]
Body, Interior / Exterior - [seats]	UNDERCARRIAGE, HEAD RESTRAINT, UPHOLSTERY, CABLE HARNESS, ARM REST, LUMBAR SUPPORT, REAR SEAT, FRONT SEAT, FRONT SEAT CUSHION EXTENS, FRONT SEAT BACKREST, ECU, SIX POINT SOCKET SCREW, FRAMEWORK, BACKREST FRAME, ENGINE	Lead [7439-92-1], C,C'-azodi(formamide) [123-77-3], Boric acid [10043-35-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Hexahydromethylphthalic-anhydride [25550-51-0], Melamine [108-78-1], 1-Methyl-2-pyrrolidone [872-50-4], Sodium borate, decahydrate [1303-96-4], Acrylamide [79-06-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]

Electric Power Supply / Instruments - [cable system]	CABLE HARNESS BUMPER, CABLE, CABLE HARNESS FLOOR, CABLE ENGINE COMPARTMENT, CABLE HARNESS, BRACKET, FUSE BOX HOUSING, CABLE HARNESS TAILGATE, CABLE FLOOR, CABLE IP, FLANGE NUT, CABLE HARNESS TUNNEL, BRACKET CJB	Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dinitrate [10141-05-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, SOUND MODULE, SUBWOOFER, WOOFER, AUDIO MODULE	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Cobalt(II) nitrate hexahydrate [10026-22-9], Imidazolidine-2-thione [96-45-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7]
Body, Interior / Exterior - [air conditioning]	AIR INLET, EL COMPRESSOR, IONIZER, ELECTRIC HEATER, SUN SENSOR, CLIMATE UNIT, WATER CONDENSER, BLOCK, PIPE ASSEMBLY, CHILLER, BLOCK WATER CONDENSER, PROTECTIVE CAP, HUMIDITY SENSOR, SENSOR EVAPORATOR, SENSOR HEX, SENSOR AQS, CONTROL UNIT FAN, TXV, VALVE CAP, SHUT-OFF VALVE, CHANNEL SENSOR, SENSOR PRESSURE TEMP, VALVE, PRESSURE HOSE, HARNESS, SENSOR	Lead-monoxide [1317-36-8], Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], C,C'-azodi(formamide) [123-77-3], TBBA [79-94-7]
Electric Power Supply / Instruments - [infotainment system]	DISPLAY, CONTROL UNIT, USB HUB, PRINTED CIRCUIT BOARD	Boric acid [10043-35-3], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [cable system high voltage]	CABLE CHARGE POINT HV, CABLE HARNESS ENGINE, CHARGE CABLE CORD, CHARGE CABLE, CABLE HARNESS, BRACKET, CABLE HARNESS HV, CABLE HARNESS IEM DC, STRAIN RELIEF, CABLE DUCT, CHANNEL, CABLE HV	Lead [7439-92-1], Lead-monoxide [1317-36-8], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Melamine [108-78-1], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Electric Power Supply / Instruments - [battery and mounting parts]	BMS, BATTERY MODULE, CURRENT SENSOR, BATTERY CONTROL UNIT, CELL VOLTAGE TEMP NODE, BATTERY DISCONNECT UNIT, HOUSING, PLUG, BUSBAR, RAIL INLET, RAIL, BATTERY, SERVICE LID, SWITCH, FLANGE NUT, HOLDER, MAIN RELAY	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Bis(2-ethylhexyl) tetrabromophthalate [26040-51-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Alkanes, C14-17, chloro [85535-85-9], Melamine [108-78-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dodecamethylcyclohexasiloxane [540-97-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Cobalt-dinitrate [10141-05-6], Tris(2-methoxyethoxy)vinylsilane [1067-53-4], Cobalt chloride [7791-13-1]

Electric Power Supply / Instruments - [lighting]	LIGHTING, CONTROL UNIT HCM, READING LAMP, HEADLAMP, OVERHEAD CONSOLE LENS, REAR LAMP, LAMP LED, MODULE, LED MODULE, FOG LIGHT	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Melamine [108-78-1]
Electric Power Supply / Instruments - [vehicle control system]	ECU, CONTROL UNIT DOOR, LOCK BUTTON, BUTTON, ECU MODULE SEAT HEATING, SWITCH DOOR, HARDWARE, SWITCH, CONTROL PANEL 12W, SWITCH PANEL, SWITCH CRUISE CONTROL, CUT-OFF SWITCH, USB POWER OUTLET, STALK MODULE, COMBI INSTRUMENT, SWITCH WINDOW LIFT	Lead titanium zirconium oxide [12626-81-2], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Boric acid [10043-35-3], 4,4'-Isopropylidenediphenol [80-05-7], Lead-titanium-trioxide [12060-00-3]
Body, Interior / Exterior - [exterior equipment]	ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER, STOP LAMP	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Engine - [cooling system]	ELECTRIC WATER PUMP, HOSE, HOSE RADIATOR QC, FAN, THREE-WAY VALVE, COOLING MODULE, RETURN PIPE, CONDENSER, 4WAY VALVE, TEMPERATURE SENSOR, BRACKET, COOLER, SET, VALVE	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Melamine [108-78-1]
Wheel Suspension / Steering - [steering gear / wheel / shaft / column]	STEERING WHEEL, STEERING GEAR, STEERING COLUMN LOCK, STEERING COLUMN MANUAL	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclotetrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], 4,4'-Isopropylidenediphenol [80-05-7]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT MKC1, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Body, Interior / Exterior - [tool / jack]	COMPRESSOR, JACK	Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclotetrasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], Ethylenediamine [107-15-3]

Electric Power Supply / Instruments - [electric drive system]	INVERTER TRANSDUCER, INVERTER, ONBOARD CHARGER, VOLTAGE CONVERTER, BRACKET, FUSE, FLANGE SCREW	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Terphenyl, hydrogenated [61788-32-7], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methylimidazole [693-98-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 4-Nonylphenol, branched [84852-15-3], N,N-Dimethylacetamide [127-19-5], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [instrument / radio panel]	DECOR WOOD, LIGHTNING INSTRUMENT PANEL, PANEL NOZZLE, INSTRUMENT PANEL, FRAME, HINGE PIN, GLOVE BOX, LED MODULE, DIM COOLING	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [instruction / information plates]	NUMBER PLATE HOLDER, DECAL SRS	Lead [7439-92-1], 2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], Imidazolidine-2-thione [96-45-7]
Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR, CAMERA, REAR VIEW MIRROR OUTER, MOTOR UNIT, GLASS	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], Dicyclohexyl-phthalate [84-61-7], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt-dinitrate [10141-05-6]
Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, TRM, HARNESS	Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	CARRIER, WELD SEALANT CURING, ADHESIVE, WELD NUT	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Boric acid [10043-35-3]
Power Transmission - [electrical axis drive]	FRONT AXLE, REAR AXLE, INNER HOUSING, OUTER HOUSING, BRACKET, ELECTRIC MOTOR, O-RING, INVERTER, FLANGE SCREW, TRANSMISSION HOUSE, PLUG, PLANET CARRIER	Lead [7439-92-1], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]

Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE REAR, BRAKE PIPE ENGINE COMPART, BRAKE PIPE FRONT	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [trunk lid / tailgate complete]	TAILGATE, ANTIFLUTTER, SPINDLE DRIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, REAR SCREEN	Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1]
Engine - [engine / engine mounting]	BRACKET ENGINE MOUNT, ENGINE MOUNT, FRONT AXLE, ELECTRIC MOTOR, REAR AXLE, INNER HOUSING, OUTER HOUSING, BRACKET, O-RING, STRAIN RELIEF, CABLE HARNESS	Lead [7439-92-1], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], Decamethylcyclotetrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, WIRELESS CHARGE SYSTEM, BATTERY, ANTENNA, BACK-UP BATTERY, AUXILIARY TELEMATIC, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], N,N-Dimethylacetamide [127-19-5], Dioctyltin dilaurate [3648-18-8]
Body, Interior / Exterior - [interior equipment]	ARM REST, EC REAR VIEW MIRROR, DAWN, AIR OUTLET, CUP HOLDER, REAR BRACKET, BRACKET	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Cobalt sulphate [10124-43-3], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4]
Electric Power Supply / Instruments - [automatic monitoring / control]	CONTROL UNIT, RAIN SENSOR, REMOTE KEY, TRM, SIREN, PRINTED CIRCUIT BOARD, SENSOR	Lead-monoxide [1317-36-8], Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Diboron-trioxide [1303-86-2], Lead(II,IV)-oxide [1314-41-6], TBBA [79-94-7]
Body, Interior / Exterior - [seat belt / other restraining systems]	HEIGHT ADJUSTMENT, SEAT BELT, BELT, BELT CATCH	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dinitrate [10141-05-6], TBBA [79-94-7], Lead-monoxide [1317-36-8]

Electric Power Supply / Instruments - [electric drive system, high voltage]	CELL VOLTAGE TEMP NODE, BATTERY CONTROL UNIT	Diboron-trioxide [1303-86-2], Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Lead-monoxide [1317-36-8]
Frame / Springs / Damping / Wheels - [rim]	ADHESIVE BALANCE WEIGHT, KEY, WHEEL BOLT	Diboron-trioxide [1303-86-2], Lead [7439-92-1], 2-Methylimidazole [693-98-1]
Wheel Suspension / Steering - [axle member / link arm / suspension]	BUSHING	Lead [7439-92-1]
Engine - [control systems]	CONTROL UNIT	Lead-monoxide [1317-36-8], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, WAVE TRAP, GROUND SIDE COIL, ETC ON BOARD UNIT, ANTENNA, ETC MODULE	Lead-monoxide [1317-36-8], Lead [7439-92-1], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 4,4'-Isopropylidenediphenol [80-05-7], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9]
Brake - [wheel brake]	BRAKE CALIPER, HOUSING, AIR VENTING NIPPLE, EPB, BLEEDER VALVE	Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0]
Body, Interior / Exterior - [airbag]	CONTROL UNIT SRS, CONTROL UNIT, AIRBAG, AIRBAG MODULE	Lead-monoxide [1317-36-8], Lead [7439-92-1], Refractory ceramic fibres [142844-00-6], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [hood cover]	HOOD, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION, SEALANT REPAIR	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4]
Body, Interior / Exterior - [roof]	ADHESIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [body side]	ADHESIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Brake - [brake control]	BRAKE LIGHT SWITCH	Lead [7439-92-1]

Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK ANTI-ROLL BAR	Imidazolidine-2-thione [96-45-7]
Electric Power Supply / Instruments - [protection]	SENSOR	Lead [7439-92-1], Lead-monoxide [1317-36-8]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	COVER	Lead [7439-92-1]
Electric Power Supply / Instruments - [horn]	HORN	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [climate unit]	CONTROL UNIT	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2]