

V90CC MODEL YEAR 2023
Candidate List Substances Table

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2022 week 40.

| Localisation | Partnames | Substance/s |
|--|--|---|
| Body, Interior / Exterior - [air conditioning] | CLIMATE UNIT, FUEL OPERATED HEATER, IONIZER, SUN SENSOR, SENSOR, PROTECTIVE CAP, VALVE, HUMIDITY SENSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, FAN, PIPE ASSEMBLY, AIR CLEANER, AIR INLET, VALVE CAP, CHANNEL SENSOR, CONTROL VALVE, MAGNET CLUTCH, AC-COMPRESSOR, SENSOR INTERIOR, FUEL PUMP | 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Lead [7439-92-1], Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Octamethylcyclotetrasiloxane [556-67-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9] |
| Body, Interior / Exterior - [airbag] | ACCELEROMETER SENSOR, CONTROL UNIT | Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3] |
| Body, Interior / Exterior - [body side] | WELD SEALANT CURING, ADHESIVE | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1] |
| Body, Interior / Exterior - [bonnet / cover with assembly parts] | HOOD LOCK, COVER, FOAM, HOOD RELEASE CABLE, HOOD LOCK CONTROL | Lead [7439-92-1], C,C'-azodi(formamide) [123-77-3], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Imidazolidine-2-thione [96-45-7] |
| Body, Interior / Exterior - [exterior equipment] | ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER | Diboron-trioxide [1303-86-2], Lead [7439-92-1] |
| Body, Interior / Exterior - [floor / frame section / wheel housing / firewall] | BUMPER BEAM, FRONT SIDE MEMBER, WHEEL HOUSING, WELD SEALANT CURING, ADHESIVE, TOP COVER, REINFORCEMENT, SIDE MEMBER UPPER INNER, BRACE INNER, BRACE OUTER, CRASH BOX REINFORCEMENT, FLOOR PANEL, BATTERY TRAY, CRASH BOX | Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1] |
| Body, Interior / Exterior - [front fender] | SHIM, FRONT FENDER | Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1] |
| Body, Interior / Exterior - [glass, window / windscreen / roof] | WINDSCREEN, GLASS HARDENED, GLASS LAMINATED, REAR SCREEN, QUARTER GLASS HARDENED, QUARTER GLASS LAMINATED | Diboron-trioxide [1303-86-2], Lead [7439-92-1] |
| Body, Interior / Exterior - [hood cover] | FOAM, HOOD | C,C'-azodi(formamide) [123-77-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1] |

| | | |
|---|---|--|
| Body, Interior / Exterior - [instruction / information plates] | NUMBER PLATE HOLDER, DECAL SRS, SIX POINT SOCKET SCREW | Imidazolidine-2-thione [96-45-7], 2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], 1-Methyl-2-pyrrolidone [872-50-4] |
| Body, Interior / Exterior - [instrument / radio panel] | STORAGE BOX, HINGE PIN, LAMP LED, CONCEALING PANEL, GLOVE BOX | Lead [7439-92-1] |
| Body, Interior / Exterior - [interior equipment] | PADDING, ARM REST, JALUSIE, CUP HOLDER, EC REAR VIEW MIRROR, COURTESY HANDLE, DAMPER, HINGE, SIDE PANEL, LIGHTING, LED MODULE, FRAMEWORK | C,C'-azodi(formamide) [123-77-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], Cobalt-dinitrate [10141-05-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1] |
| Body, Interior / Exterior - [lock / handle] | DOOR LOCK, LOCK WITH ANTI THEFT COVE, LOCK, OUTER HANDLE, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, HANDLE, LOCK CYLINDER | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Hexahydromethylphthalic-anhydride [25550-51-0], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9] |
| Body, Interior / Exterior - [miscellaneous] | TRANSPORT PROTECTION, SEALANT REPAIR, SEALING, SOUND INSULATION | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2] |
| Body, Interior / Exterior - [outside mirrors] | CAMERA, REAR VIEW MIRROR OUTER, REAR VIEW MIRROR, MOTOR UNIT, DIRECTION INDICATOR, TEMPERATURE SENSOR, GLASS | 2-Methylimidazole [693-98-1], Lead [7439-92-1], Dicyclohexyl-phthalate [84-61-7], Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Tris(nonylphenyl)phosphite [26523-78-4] |
| Body, Interior / Exterior - [recovery / towing unit] | TOWING HOOK, TRM, HARNESS | Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Lead-monoxide [1317-36-8] |
| Body, Interior / Exterior - [roof] | PANORAMA ROOF, GLASS PANEL, WELD SEALANT CURING, ADHESIVE ROOF HATCH, MOTOR | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8] |
| Body, Interior / Exterior - [seat belt / other restraining systems] | HEIGHT ADJUSTMENT, BELT CATCH, SEAT BELT, LOAD NET, BELT CATCH REAR, BELT | Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1] |
| Body, Interior / Exterior - [seats] | FRAMEWORK, HEAD RESTRAINT, UPHOLSTERY, HARDBACK, UNDERCARRIAGE, ARM REST, ENGINE TILT, ENGINE, HEATING PAD SEAT, VENTILATION, LUMBAR SUPPORT, STS SENSOR, MASSAGE UNIT, SIDE BOLSTER, BACKREST FRAME, HEATER, CABLE HARNESS, SIX POINT SOCKET SCREW, FRAME, FAN, LUMBAR SUPPORT 4-WAY | Paraffin oils, chloro [85422-92-0], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], 1-Methyl-2-pyrrolidone [872-50-4], Glutaral [111-30-8] |

| | | |
|--|---|--|
| Body, Interior / Exterior - [side door] | SIDE DOOR, WINDOW LIFT, HEMMING ADHESIVE, CARRIER PLATE, BODY MOUNTED SEALING, DOOR MOUNTED SEALING | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], Imidazolidine-2-thione [96-45-7], C,C'-azodi(formamide) [123-77-3] |
| Body, Interior / Exterior - [tank hatch] | ACTUATOR, PLASTIC MODULE | Lead [7439-92-1] |
| Body, Interior / Exterior - [trunk lid / tailgate complete] | REAR DOOR, SPINDLE DRIVE | Lead [7439-92-1], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8] |
| Body, Interior / Exterior - [upholstery] | DOOR PANEL, SILL MOULDING, WAISTRAIL, LIGHTING, LAMP LED, SILL FRONT, RUBBER MAT, RUBBER SEAL, GUIDE RAIL, SIDE PANEL, FLOOR HATCH, PANEL, TRUNK FLOOR SUPPORT, HEADLINING, LUGGAGE COVER | C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1] |
| Brake - [brake control] | SENSOR, PEDAL UNIT | Lead [7439-92-1] |
| Brake - [brake line with connections] | BRAKE PIPE, BRAKE PIPE FRONT, BRAKE PIPE REAR | Lead [7439-92-1] |
| Brake - [brake, anti lock (anti-skid)] | HYDRAULIC UNIT, SENSOR | Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-titanium-trioxide [12060-00-3] |
| Brake - [wheel brake] | BRAKE CALIPER, AIR VENTING NIPPLE, EPB, BLEEDER VALVE, HOUSING | Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0] |
| Electric Power Supply / Instruments - [antenna] | ANTENNA AMPLIFIER, ETC ON BOARD UNIT, ANTENNA, ETC MODULE | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1] |
| Electric Power Supply / Instruments - [automatic monitoring / control] | SIREN, RAIN SENSOR, CONTROL UNIT, REMOTE KEY, SENSOR | Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead(II,IV)-oxide [1314-41-6], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3] |
| Electric Power Supply / Instruments - [battery and mounting parts] | BMS, BATTERY, SWITCH | Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,3-Propanesultone [1120-71-4] |
| Electric Power Supply / Instruments - [cable system high voltage] | CHARGE CABLE CORD | Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8] |

| | | |
|--|---|--|
| Electric Power Supply / Instruments - [cable system] | CABLE, CABLE HARNESS, CABLE FLOOR, CABLE HARNESS WEM, CABLE HARNESS TAILGATE, CABLE DUCT, BRACKET, FLANGE NUT, DISCONNECTOR POWER, FUSE BOX ASSY, CABLE PAC, FUSE BOX, CABLE INFOTAINMENT | Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Tris(nonylphenyl)phosphite [26523-78-4], Cobalt-dinitrate [10141-05-6], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Paraffin oils, chloro [85422-92-0], Dicyclohexyl-phthalate [84-61-7], 4,4'-Isopropylidenediphenol [80-05-7] |
| Electric Power Supply / Instruments - [cleaner] | WIPER UNIT, WASHER FLUID RESERVOIR, REAR WIPER, HEADLAMP WIPER, PUMP, DUAL PUMP, WIPER ARM | Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2] |
| Electric Power Supply / Instruments - [communication, mobile telephone] | CONTROL UNIT, WIRELESS CHARGE SYSTEM, BATTERY, PRINTED CIRCUIT BOARD | Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] |
| Electric Power Supply / Instruments - [electric drive system] | VOLTAGE CONVERTER, STARTER MOTOR ALTERNATOR, COOLANT PIPE, SENSOR, STARTER MOTOR, BRACKET | Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], N,N-Dimethylacetamide [127-19-5] |
| Electric Power Supply / Instruments - [electrical distribution box / fuse box] | ATTACHMENT, CEM | Lead [7439-92-1] |
| Electric Power Supply / Instruments - [horn] | HORN | Lead [7439-92-1], Diboron-trioxide [1303-86-2] |
| Electric Power Supply / Instruments - [infotainment system] | DISPLAY, GRAPHIC HEAD UP DISPLAY, CONTROL UNIT, USB HUB, PRINTED CIRCUIT BOARD | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-titanium-trioxide [12060-00-3], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Silicic acid, lead salt [11120-22-2], Boric acid [10043-35-3] |
| Electric Power Supply / Instruments - [lighting] | CONTROL UNIT HCM, HEADLAMP, OVERHEAD CONSOLE LENS, READING LAMP, LIGHTING, LIGHTNING INSTRUMENT PANEL, LED MODULE, STOP LAMP, LAMP LED, REAR LAMP, FOG LIGHT | Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Dicyclohexyl-phthalate [84-61-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-titanium-trioxide [12060-00-3] |
| Electric Power Supply / Instruments - [mobile data services] | CONTROL UNIT | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1] |
| Electric Power Supply / Instruments - [protection] | CONTROL UNIT, SENSOR REAR, SENSOR FRONT, ACCELEROMETER FRONT | Lead [7439-92-1] |

| | | |
|---|---|---|
| Electric Power Supply / Instruments - [radio equipment] | MICROPHONE, SPEAKER MIDRANGE, AUDIO MODULE, BRACKET, SUBWOOFER, WOOFER, LOUDSPEAKER, CENTRE LOUDSPEAKER | Diboron-trioxide [1303-86-2], Lead [7439-92-1], N,N-Dimethylacetamide [127-19-5], Cobalt(II) nitrate hexahydrate [10026-22-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7] |
| Electric Power Supply / Instruments - [starting system] | STARTER MOTOR | Lead [7439-92-1] |
| Electric Power Supply / Instruments - [support systems] | SENSOR, CONTROL UNIT, CAMERA, RADAR | Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], Lead-titanium-trioxide [12060-00-3], Dicyclohexyl-phthalate [84-61-7], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6] |
| Electric Power Supply / Instruments - [vehicle computational units / gateway modules] | CONTROL UNIT | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8] |
| Electric Power Supply / Instruments - [vehicle control system] | SWITCH PANEL, CONTROL UNIT DOOR, BUTTON, ECU, STALK MODULE, HARDWARE, SWITCH, LOCK BUTTON, LOCK BUTTON LED, COMBI INSTRUMENT, CUT-OFF SWITCH, USB POWER OUTLET, SWITCH WINDOW LIFT, GEAR SHIFT PADDLE, SWITCH DOOR, SWITCH MODULE, SWITCH STEERING WHEEL | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Boric acid [10043-35-3], 4,4'-Isopropylidenediphenol [80-05-7] |
| Engine - [accelerator control] | ACCELERATOR PEDAL | Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8] |
| Engine - [air cleaner] | RESONATOR, HOSE MODULE | Lead [7439-92-1] |
| Engine - [cold zone / batterybox] | NVH PANEL | Lead [7439-92-1] |
| Engine - [control systems] | TEMP AND PRESSURE SENSOR, AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, PRESSURE SENSOR | Lead [7439-92-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Lead titanium zirconium oxide [12626-81-2] |
| Engine - [cooling system] | TWO-WAY VALVE, VALVE, HOSE TEMP SENSOR, HOSE OUTLET, HOSE MODULE, TWIN CLIP, WATER PUMP, COOLER, CONDENSER, RADIATOR, CHARGE AIR COOLER, TEMPERATURE SENSOR, BLEEDER HOSE, PUMP, THREE-WAY VALVE, BRACKET, CLAMP BRACKET, HOSE, RETAINER, HEATER HOSE, PIPE, COMPLETE COOLER, PRESSURE SENSOR, HOSE HEATER, HOSE INLET, OUTLET HOSE, THERMOSTAT HOUSING, NIPPLE, INLET PIPE, PLASTIC PIPE, COVER, SIX POINT SOCKET SCREW, MODULE WATER PUMP, BRACKET TEMP SENSOR, O-RING, STRIKER PLATE | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclopentasiloxane [541-02-6], 1-Methyl-2-pyrrolidone [872-50-4], Paraffin oils, chloro [85422-92-0], Lead titanium zirconium oxide [12626-81-2], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Lead(II,IV)-oxide [1314-41-6], C,C'-azodi(formamide) [123-77-3], Octamethylcyclotetrasiloxane [556-67-2] |

| | | |
|---|--|---|
| Engine - [crank mechanism] | DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE | Lead [7439-92-1] |
| Engine - [cylinder block / head] | CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN | Lead [7439-92-1] |
| Engine - [distributor] | CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR | Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2] |
| Engine - [emission equipment] | COOLER, PRESSURE SENSOR, VALVE, TEMPERATURE SENSOR EGT, TEMPERATURE SENSOR | Lead [7439-92-1], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2] |
| Engine - [engine / engine mounting] | ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET | Lead [7439-92-1] |
| Engine - [fan] | FAN, FAN LOW | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2] |
| Engine - [fuel / EVAP system] | FUEL PUMP MODULE, PURGE VALVE, LEAK DETECTION PUMP, PURGE VALVE ASSY, CANISTER, FUEL PRESSURE SENSOR, HOSE, FUEL FILTER, FUEL TANK, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, FUEL PUMP, DELIVERY PIPE, INJECTOR, INJECTION VALVE | Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dinitrate [10141-05-6] |
| Engine - [ignition / spark plug] | GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8] |
| Engine - [inlet / exhaust systems] | TAILPIPE, THROTTLE, EXHAUST SYSTEM, HEAT SHIELD PLATE, INTAKE MANIFOLD | Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] |
| Engine - [intercooler / connection] | CHARGE AIR COOLER, CHARGE AIR HOSE, CHARGE AIR PIPE, RESONATOR | Lead [7439-92-1], Boric acid [10043-35-3] |
| Engine - [lubricating and oil system] | OIL SUMP, SUCTION LINE, OIL PUMP, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, PISTON COOLING JET, OIL FILTER, PLUG, OIL PRESSURE SENSOR | Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2] |
| Engine - [miscellaneous / help device installation] | SPLASH PROTECTION, BRACKET, TENSIONER, GUIDE SLEEVE | Lead [7439-92-1] |

| | | |
|---|--|---|
| Engine - [selective catalytic reduction] | CONTROL UNIT, SENSOR, PUMP MODULE, BRACKET, TANK, CONTROL MODULE | Lead [7439-92-1], Nonylphenol [25154-52-3], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2] |
| Engine - [supercharging] | SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, O-RING, MP TURBO, INLET PIPE | Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Lead-monoxide [1317-36-8], Dicyclohexyl-phthalate [84-61-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Diboron-trioxide [1303-86-2] |
| Engine - [transmission] | TENSIONER, CAMSHAFT, IDLER PULLEY, BALANCE SHAFT, SOLENOID, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE | Lead [7439-92-1] |
| Frame / Springs / Damping / Wheels - [anti-roll bar] | LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR REAR, ANTI-ROLL BAR FRONT | Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1] |
| Frame / Springs / Damping / Wheels - [rim] | KEY, WHEEL BOLT | Lead [7439-92-1] |
| Frame / Springs / Damping / Wheels - [shock absorber] | SHOCK ABSORBER FRONT, TOPMOUNT, SHOCK ABSORBER, SHOCK ABSORBER REAR | Lead [7439-92-1] |
| Frame / Springs / Damping / Wheels - [spring, leaf spring] | RESEVOIR, HOSE COUPLING, VALVE BLOCK, AIR SPRING REAR, TOPMOUNT, COMPRESSOR | Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6] |
| Power Transmission - [final drive] | BRACKET, PT-UNIT | Lead [7439-92-1] |
| Power Transmission - [front axle / rear axle / drive shaft] | AOC, DRIVE SHAFT, VIBRATION DAMPER, BRACKET, FINAL DRIVE, REAR AXLE, BEARING ANCHORAGE, FLANGE SCREW | Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9] |
| Power Transmission - [gear lever carrier / gear selector controls] | GEAR LEVER CARRIER | Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1] |
| Power Transmission - [gearbox] | TORQUE CONVERTER, VALVE BODY, CABLE HARNESS, CONTROL UNIT | Lead [7439-92-1], Lead-monoxide [1317-36-8], Nonylphenol [25154-52-3], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2] |
| Wheel Suspension / Steering - [axle member / link arm / suspension] | LOWER LINK ARM, SUBFRAME FRONT, UPPER LINK ARM | Imidazolidine-2-thione [96-45-7], Cobalt-dichloride [7646-79-9], Lead [7439-92-1] |

| | | |
|--|--|--|
| Wheel Suspension / Steering [steering gear / wheel / shaft / column] | STEERING WHEEL, STEERING WHEEL RIM, STEERING COLUMN LOCK, STEERING GEAR, STEERING WHEEL HARNESS, STEERING COLUMN | Dicyclohexyl-phthalate [84-61-7], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2] |
|--|--|--|