

**XC90 MODEL YEAR 2024**  
**Candidate List Substances Table**

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2023 week 17

Localisation	Partnames	Substance/s
Engine - [cooling system]	PUMP, HOSE, HOSE COLD ZONE, TWO-WAY VALVE, VALVE, HOSE TEMP SENSOR, HOSE OUTLET, HOSE MODULE, TWIN CLIP, WATER PUMP, COOLER, CONDENSER, SET, RADIATOR HYBRID, TEMPERATURE SENSOR, RADIATOR, CHARGE AIR COOLER, SEPARATOR, BRACKET, THREE-WAY VALVE, CLAMP BRACKET, GROMMET, RETAINER, HEATER HOSE, PIPE, EL WATER PUMP, PRESSURE SENSOR, HOSE HEATER, HOSE INLET, OUTLET HOSE, THERMOSTAT HOUSING, O-RING, NIPPLE, INLET PIPE, PLASTIC PIPE, COVER, SIX POINT SOCKET SCREW, MODULE WATER PUMP, BRACKET TEMP SENSOR, STRIKER PLATE	TBBA [79-94-7], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclotetrasiloxane [541-02-6], Melamine [108-78-1], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Octamethylcyclotetrasiloxane [556-67-2], Lead(II,IV)-oxide [1314-41-6], C,C'-azodi(formamide) [123-77-3]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, BOX, RADAR	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclotetrasiloxane [541-02-6]
Body, Interior / Exterior - [lock / handle]	OUTER HANDLE, DOOR LOCK, LOCK, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, WASHER NOZZLE, LOCK CYLINDER	Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Hexahydromethylphthalic-anhydride [25550-51-0], Melamine [108-78-1]
Wheel Suspension / Steering [steering gear / wheel / shaft / column]	STEERING WHEEL, STEERING WHEEL RIM, STEERING COLUMN LOCK, STEERING COLUMN MANUAL, STEERING GEAR, STEERING WHEEL HARNESS, STEERING GEAR EPAS	Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclotetrasiloxane [541-02-6]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, SPEAKER MIDRANGE, AUDIO MODULE, SOUND MODULE, BRACKET, SUBWOOFER, WOOFER, LOUDSPEAKER, CENTRE LOUDSPEAKER	Diboron-trioxide [1303-86-2], Lead [7439-92-1], N,N-Dimethylacetamide [127-19-5], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Cobalt(II) nitrate hexahydrate [10026-22-9], Imidazolidine-2-thione [96-45-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]

Body, Interior / Exterior - [air conditioning]	CLIMATE UNIT, PIPE ASSEMBLY, FUEL OPERATED HEATER, IONIZER, SUN SENSOR, EL COMPRESSOR, SENSOR, ELECTRIC HEATER, AIR CONDITIONING, PROTECTIVE CAP, SOLENOID CLUTCH, HUMIDITY SENSOR, AIR DUCT, SENSOR KIT, EVAPORATOR, DEFROSTER, EXPANSION VALVE, STEPPING MOTOR, FAN, CHILLER, CONTROL UNIT, AC-COMPRESSOR, FLANGE SCREW, AIR CLEANER, AIR INLET, VALVE, VALVE CAP, CONTROL VALVE, CHANNEL SENSOR, MAGNET CLUTCH, SENSOR INTERIOR, POWER UNIT, FUEL PUMP	TBBA [79-94-7], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1-Methyl-2-pyrrolidone [872-50-4], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dichloride [7646-79-9], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], Octamethylcyclotetrasiloxane [556-67-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
Engine - [fan]	FAN, FAN HIGH	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [seats]	HEAD RESTRAINT, UPHOLSTERY, UNDERCARRIAGE, OUTER SECTION REAR, ENGINE TILT, ENGINE, HEATING PAD SEAT, VENTILATION, LUMBAR SUPPORT, STS SENSOR, MASSAGE UNIT, BACKREST FRAME, VINYL, PANEL, LEATHER, FOIL, CABLE HARNESS, HEATER, ARM REST, LOCK, CUP HOLDER, FAN, LUMBAR SUPPORT 4-WAY, WIRE, STRUCTURE, SIDE BOLSTER	C,C'-azodi(formamide) [123-77-3], Glutaral [111-30-8], Lead [7439-92-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], TBBA [79-94-7], Melamine [108-78-1], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3]
Power Transmission - [electrical axis drive]	DRIVE SHAFT, CABLE HARNESS, REAR AXLE, SERVICE KIT, TWIN DISC CLUTCH, TRANSMISSION HOUSE, PLANET CARRIER, PLUG	Lead [7439-92-1], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Power Transmission - [front axle / rear axle / drive shaft]	DRIVE SHAFT, AOC, PUMP UNIT, VIBRATION DAMPER, CABLE HARNESS, REAR AXLE, FEEDER PUMP KIT, BRACKET, FINAL DRIVE, BEARING ANCHORAGE, FLANGE SCREW	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Melamine [108-78-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Cobalt-dichloride [7646-79-9]
Electric Power Supply / Instruments - [lighting]	OVERHEAD CONSOLE LENS, CONTROL UNIT HCM, REAR LAMP, HEADLAMP, READING LAMP, LIGHTING, LIGHTNING INSTRUMENT PANEL, BULB UNIT, LED MODULE, LAMP LED, FOG LIGHT, STOP LAMP	Lead [7439-92-1], TBBA [79-94-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Dicyclohexyl-phthalate [84-61-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Octamethylcyclotetrasiloxane [556-67-2], Lead-titanium-trioxide [12060-00-3]

Electric Power Supply / Instruments - [vehicle control system]	HARDWARE, SWITCH PANEL, CONTROL UNIT DOOR, SWITCH, BUTTON, ECU, STALK MODULE, LOCK BUTTON, LOCK BUTTON LED, COMBI INSTRUMENT, CUT-OFF SWITCH, USB POWER OUTLET, SWITCH WINDOW LIFT, GEAR SHIFT PADDLE, CONTROL PANEL POWER SEAT, SWITCH DOOR, SWITCH MODULE, SWITCH STEERING WHEEL	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Boric acid [10043-35-3], Lead [7439-92-1], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 4,4'-Isopropylidenediphenol [80-05-7]
Body, Interior / Exterior - [interior equipment]	PADDING, ARM REST, CUP HOLDER, EC REAR VIEW MIRROR, SIDE PANEL, DAMPER, HINGE, LIGHTING, LED MODULE, FRAMEWORK	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [air cleaner]	FRESH AIR PIPE, HOSE FRESH AIR PIPE, BOX, RESONATOR, HOSE MODULE	Lead [7439-92-1]
Engine - [fuel / EVAP system]	PURGE VALVE ASSY, FUEL PUMP MODULE, PUMP MODULE, JET PUMP AND LEVEL SENSOR, EVAP PURGE PUMP, PURGE VALVE, LEAK DETECTION PUMP, ISOLATION VALVE, CANISTER, FUEL PRESSURE SENSOR, HOSE, FUEL FILTER, FUEL TANK, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, FUEL PUMP, DELIVERY PIPE, INJECTOR, INJECTION VALVE	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dinitrate [10141-05-6]
Electric Power Supply / Instruments - [infotainment system]	DISPLAY, GRAPHIC HEAD UP DISPLAY, CONTROL UNIT, USB HUB, PRINTED CIRCUIT BOARD, TV TUNER	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafuoro-, potassium salt (1:1) [29420-49-3], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], Boric acid [10043-35-3], Silicic acid, lead salt [11120-22-2]
Body, Interior / Exterior - [front fender]	SHIM, FRONT FENDER	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [control systems]	TEMP AND PRESSURE SENSOR, AIR TEMP SENSOR, CONTROL UNIT, PRESSURE SENSOR, MASS AIR FLOW SENSOR	Lead [7439-92-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Dicyclohexyl-phthalate [84-61-7], Acrylamide [79-06-1], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3]
Body, Interior / Exterior - [outside / exterior trim]	SENSOR	Lead [7439-92-1], Lead-monoxide [1317-36-8]
Electric Power Supply / Instruments - [cable system high voltage]	STRAIN RELIEF, CABLE CHARGE POINT HV, CABLE HARNESS, BRACKET, CABLE DUCT, RETAINER, CHANNEL, CHARGE CABLE CORD, CABLE CHANNEL, CHARGE CABLE	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Octamethylcyclotetrasiloxane [556-67-2], TBBA [79-94-7], Melamine [108-78-1]

Electric Power Supply / Instruments - [cable components]	STRAIN RELIEF, FUSE BOX, CABLE DUCT, RECEPTACLE HOUSING, UNLOADING CABLE, PRINTED CIRCUIT BOARD, EJB, DISCONNECTOR POWER, CABLE, CABLE CHANNEL, BATTERY TERMINAL, FUSE BOX ASSY, SPLICE, FUSE BOX REAR, RETAINER, CHANNEL, AIR HOSE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Octamethylcyclotetrasiloxane [556-67-2]
Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, TAILPIPE, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [battery and mounting parts]	BMS, RBMS, CURRENT SENSOR, BATTERY, FILTER BOARD ASSY, MODULE, SWITCH, CONTROL UNIT, BATTERY 48V, COVER, HEAT INSULATION PAD, SERVICE SWITCH, INLET HOSE, OUTLET HOSE, FILTER BOARD, HEAT SHIELD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,3-Propanesultone [1120-71-4], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Melamine [108-78-1], Boric acid [10043-35-3], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3]
Engine - [selective catalytic reduction]	CONTROL UNIT, SENSOR, PUMP MODULE, BRACKET, TANK, CONTROL MODULE	Lead [7439-92-1], Nonylphenol [25154-52-3], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2]
Body, Interior / Exterior - [tank hatch]	ACTUATOR, PLASTIC MODULE	Lead [7439-92-1], TBBA [79-94-7]
Electric Power Supply / Instruments - [cable system]	CABLE, CABLE HARNESS, CABLE HARNESS WEM, CABLE FLOOR, CABLE DUCT, FUSE BOX, EJB, FLANGE NUT, DISCONNECTOR POWER, CABLE INFOTAINMENT, CABLE TELE, FUSE BOX ASSY, CABLE PAC, CABLE HARNESS BUMPER, CABLE CAN, BRACKET, PRINTED CIRCUIT BOARD	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 4,4'-Isopropylidenediphenol [80-05-7], Cobalt-dinitrate [10141-05-6], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
Body, Interior / Exterior - [recovery / towing unit]	HARNESS, TOWING HOOK, TRM	Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Lead-monoxide [1317-36-8], TBBA [79-94-7]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, BRACKET, GEAR LEVER KNOB, GEAR SHIFT CABLE, INSERT, HOUSING, ACTUATOR	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], 4,4'-Isopropylidenediphenol [80-05-7], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7]

Electric Power Supply / Instruments - [antenna]	BLUETOOTH ANTENNA, SPOILER ANTENNA, ANTENNA AMPLIFIER, MAM ANTENNA MODULE, ANTENNA, ETC ON BOARD UNIT, ETC MODULE	Lead [7439-92-1], Alkanes, C14-17, chloro [85535-85-9], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Body, Interior / Exterior - [exterior equipment]	SPOILER ANTENNA, SPOILER, STOP LAMP, ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Alkanes, C14-17, chloro [85535-85-9], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2]
Frame / Springs / Damping / Wheels - [shock absorber]	SHOCK ABSORBER REAR, SHOCK ABSORBER FRONT, TOPMOUNT	Lead [7439-92-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, BRAKE PIPE REAR, FILLER PIPE	Lead [7439-92-1]
Engine - [engine / engine mounting]	ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET, FRONT AXLE, ELECTRIC MOTOR, REAR AXLE, INNER HOUSING, OUTER HOUSING, BRACKET, O-RING, STRAIN RELIEF, CABLE HARNESS	Lead [7439-92-1], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], Decamethylcyclotrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	WHEEL HOUSING, FRONT SIDE MEMBER, ADHESIVE, TOP COVER, BACK PANEL, BRACE INNER, BRACE OUTER, REINF BRACE OUTER, SIDE MEMBER UPPER INNER, BATTERY TRAY, BATTERY BOX	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD LOCK, COVER, HOOD RELEASE CABLE, HOOD LOCK CONTROL	Lead [7439-92-1], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Imidazolidine-2-thione [96-45-7]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Power Transmission - [gearbox]	TORQUE CONVERTER, AUTOMATIC GEARBOX, CONTROL UNIT, VALVE BODY, CABLE HARNESS, CONNECTOR, SERVO COVER, CONTROL SYSTEM, OIL PUMP, ADAPTER, FLANGE NUT, DIFFERENTIAL SPACER, LID, FLANGE SCREW	Lead [7439-92-1], Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Diboron-trioxide [1303-86-2], Nonylphenol [25154-52-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Cobalt-dinitrate [10141-05-6], Cobalt-dichloride [7646-79-9], Silicic acid, lead salt [11120-22-2]

Body, Interior / Exterior - [upholstery]	DOOR PANEL, FLOOR HATCH, PANEL, LIGHTING, LAMP LED, SILL FRONT, LED MODULE, SILL MOULDING	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Tris(nonylphenyl)phosphite [26523-78-4], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [automatic monitoring / control]	RAIN SENSOR, CONTROL UNIT, REMOTE KEY, SENSOR, SIREN	Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methylimidazole [693-98-1], Melamine [108-78-1]
Body, Interior / Exterior - [seat belt / other restraining systems]	SEAT BELT, HEIGHT ADJUSTMENT, BELT CATCH, BELT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [trunk lid / tailgate complete]	SPINDLE DRIVE, TAILGATE	Lead [7439-92-1], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, INVERTER IEM, STARTER MOTOR ALTERNATOR, ONBOARD CHARGER, PROTECTION HIGH VOLTAGE, BRACKET, INVERTER IGM, COOLANT PIPE, SENSOR, STARTER MOTOR, FLANGE SCREW	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 1,3,5-Tris(oxiranymethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Dicyclohexyl-phthalate [84-61-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Alkanes, C14-17, chloro [85535-85-9], N,N-Dimethylacetamide [127-19-5], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [roof]	PANORAMA ROOF, GLASS PANEL, ROOF HATCH, ADHESIVE ROOF HATCH, ADHESIVE, MOTOR, SEALING, SEALING STRIP	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], C,C'-azodi(formamide) [123-77-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, PRINTED CIRCUIT BOARD, WIRELESS CHARGE SYSTEM, RETAINER, ANTENNA, BATTERY, BACK-UP BATTERY, AUXILIARY TELEMATIC	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], N,N-Dimethylacetamide [127-19-5], Dioctyltin dilaurate [3648-18-8]
Electric Power Supply / Instruments - [alternator]	ALTERNATOR 210A, REGULATOR LIN	Lead [7439-92-1], TBBA [79-94-7]

Electric Power Supply / Instruments - [cleaner]	WIPER APPARATUS, WASHER FLUID RESERVOIR, REAR WIPER, DUAL PUMP, PUMP, WIPER ARM, WIPER ARM AND BLADE	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [miscellaneous]	ABSORBER, TRANSPORT PROTECTION, SEALANT REPAIR, SOUND INSULATION	Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [glass, window / windscreen / roof]	QUARTER GLASS LAMINATED, QUARTER GLASS HARDENED, WINDSCREEN, GLASS LAMINATED, GLASS HARDENED, REAR SCREEN	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Frame / Springs / Damping / Wheels - [rim]	SENSOR, KEY, WHEEL BOLT	Lead [7439-92-1], 1,2-Dimethoxyethane [110-71-4], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2]
Engine - [emission equipment]	COOLER, STAY, PRESSURE SENSOR, VALVE, TEMPERATURE SENSOR EGT, TEMPERATURE SENSOR	Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2]
Engine - [intercooler / connection]	CHARGE AIR COOLER, CHARGE AIR PIPE, CHARGE AIR HOSE, RESONATOR	Lead [7439-92-1], Boric acid [10043-35-3]
Wheel Suspension / Steering - [axle member / link arm / suspension]	LOWER LINK ARM, UPPER LINK ARM	Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Body, Interior / Exterior - [outside mirrors]	CAMERA, REAR VIEW MIRROR OUTER, REAR VIEW MIRROR, GLASS, MOTOR UNIT, DIRECTION INDICATOR, TEMPERATURE SENSOR	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Dicyclohexyl-phthalate [84-61-7], 2-Methylimidazole [693-98-1], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Tris(nonylphenyl)phosphite [26523-78-4]
Body, Interior / Exterior - [side door]	WINDOW LIFT, HEMMING ADHESIVE, ANTIFLUTTER, SIDE DOOR	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Brake - [wheel brake]	BRAKE CALIPER, AIR VENTING NIPPLE, EPB, HOUSING, BLEEDER VALVE	Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0]
Electric Power Supply / Instruments - [protection]	SENSOR FRONT, SENSOR REAR, CONTROL UNIT, ACCELEROMETER	Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [airbag]	AIRBAG MODULE, ACCELEROMETER SENSOR, CONTROL UNIT	4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead [7439-92-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3]

Body, Interior / Exterior - [instruction / information plates]	DECAL SRS, NUMBER PLATE HOLDER, SIX POINT SOCKET SCREW	2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], Imidazolidine-2-thione [96-45-7], 1-Methyl-2-pyrrolidone [872-50-4]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING, ADHESIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Brake - [brake control]	SENSOR, PEDAL UNIT	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	RESEVOIR, AIR HOSE BUNDLE, CONNECTOR, HOSE COUPLING, VALVE BLOCK, AIR SPRING REAR, SHOCK ABSORBER FRONT, AIR SPRING FRONT, TOPMOUNT, COMPRESSOR	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Tris(nonylphenyl)phosphite [26523-78-4]
Power Transmission - [actuator, gear shift]	BOX, CONTROL UNIT	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2]
Brake - [master cylinder / brake booster]	VACUUM SENSOR, BRAKE BOOSTER, BRAKE FLUID RESERVOIR, ACTUATION UNIT, MASTER CYLINDER	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [instrument / radio panel]	STORAGE BOX, HINGE PIN, LAMP LED, LED MODULE, PANEL NOZZLE, CONCEALING PANEL, GLOVE BOX	Lead [7439-92-1], TBBA [79-94-7]
Electric Power Supply / Instruments - [starting system]	STARTER MOTOR	Lead [7439-92-1], Ethylenediamine [107-15-3]
Body, Interior / Exterior - [hood cover]	HOOD	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [miscellaneous / help device installation]	BRACKET, SPLASH PROTECTION, TENSIONER, GUIDE SLEEVE	Lead [7439-92-1]
Power Transmission - [final drive]	PT-UNIT, BRACKET	Lead [7439-92-1]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	ATTACHMENT, CEM	Lead [7439-92-1]
Electric Power Supply / Instruments - [horn]	HORN	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Brake - [vacuum pump / tank / line / valve]	VACUUM HOSE	C,C'-azodi(formamide) [123-77-3]



Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Engine - [supercharging]	SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, O-RING, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, MP TURBO, INLET PIPE	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Dicyclohexyl-phthalate [84-61-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-monoxide [1317-36-8]
Engine - [transmission]	TENSIONER, CAMSHAFT, IDLER PULLEY, BALANCE SHAFT, SOLENOID, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE	Lead [7439-92-1]
Engine - [lubricating and oil system]	OIL SUMP, SUCTION LINE, OIL PUMP, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, PISTON COOLING JET, OIL FILTER, PLUG, OIL PRESSURE SENSOR	Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Engine - [cylinder block / head]	CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [distributor]	CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]
Engine - [ignition / spark plug]	GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]