

**XC40 MODEL YEAR 2024  
Candidate List Substances Table**

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2023 week 41.

Localisation	Partnames	Substance/s
Electric Power Supply / Instruments - [cable system]	CABLE, CHANNEL, CABLE FLOOR, CABLE INFOTAINMENT, CABLE PAC, CABLE ENGINE COMPARTMENT, CABLE HARNESS, CABLE POWER TRAIN, CABLE HARNESS BUMPER, BRACKET, FUSE BOX HOUSING, CABLE HARNESS TAILGATE, CABLE IP, FLANGE NUT, CABLE LOCKING DEVICE, ADAPTER CABLE, CABLE HARNESS TUNNEL, HARNESS LOCKING DEVICE, CABLE EXTERIOR, BRACKET CJB, FUSE BOX, CABLE HARNESS ROOF	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Tris(nonylphenyl)phosphite [26523-78-4], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Cobalt-dinitrate [10141-05-6], TBBA [79-94-7]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, RADAR, EXT743	Lead-monoxide [1317-36-8], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9]
Electric Power Supply / Instruments - [cable components]	CHANNEL, FUSE BOX HOUSING, FRAME ASSY, BRACKET, STRAIN RELIEF, CABLE DUCT, RECEPTACLE HOUSING, DISCONNECTOR POWER, DIODE, FUSE BOX, BOTTOM PART, ADAPTER PLATE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SHIM, HEADLINING, REAR SHELF, SILL MOULDING	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Body, Interior / Exterior - [lock / handle]	DOOR LOCK, LOCK, OUTER HANDLE, LOCK CYLINDER SET, EXT743, KEY	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Hexahydromethylphthalic-anhydride [25550-51-0]
Body, Interior / Exterior - [side door]	CARRIER, SEALING	Lead [7439-92-1], Imidazolidine-2-thione [96-45-7], C,C'-azodi(formamide) [123-77-3]

Body, Interior / Exterior - [seats]	UNDERCARRIAGE, HEAD RESTRAINT, UPHOLSTERY, ARM REST, LUMBAR SUPPORT, REAR SEAT, FRONT SEAT, FRONT SEAT CUSHION EXTENS, CABLE HARNESS, FRONT SEAT BACKREST, ECU, SIX POINT SOCKET SCREW, FRAMEWORK, BACKREST FRAME, ENGINE	Lead [7439-92-1], C,C'-azodi(formamide) [123-77-3], Boric acid [10043-35-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Hexahydromethylphthalic-anhydride [25550-51-0], Melamine [108-78-1], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], 1-Methyl-2-pyrrolidone [872-50-4], Sodium borate, decahydrate [1303-96-4], Acrylamide [79-06-1], N,N-Dimethylacetamide [127-19-5], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, INSERT, GEAR SHIFT CABLE, ACTUATOR	Lead [7439-92-1], Lead-monoxide [1317-36-8], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, AUDIO MODULE, SOUND MODULE, SUBWOOFER, WOOFER	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Cobalt(II) nitrate hexahydrate [10026-22-9], Imidazolidine-2-thione [96-45-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7]
Body, Interior / Exterior - [air conditioning]	AIR INLET, EL COMPRESSOR, FUEL OPERATED HEATER, IONIZER, ELECTRIC HEATER, SUN SENSOR, CONDENSER, CLIMATE UNIT, WATER CONDENSER, BLOCK, PIPE ASSEMBLY, CHILLER, BLOCK WATER CONDENSER, PROTECTIVE CAP, HUMIDITY SENSOR, SOLENOID CLUTCH, FILTER INSERT, AC-COMPRESSOR, SENSOR EVAPORATOR, SENSOR HEX, SENSOR AQS, CONTROL UNIT FAN, TXV, TXV W, VALVE, VALVE CAP, SHUT-OFF VALVE, CONTROL VALVE, PTC, FUEL PUMP, CHANNEL SENSOR, SENSOR PRESSURE TEMP, PRESSURE HOSE, PRESSURE SENSOR, HARNESS, FAN HOUSING, SENSOR	Lead-monoxide [1317-36-8], Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], Decamethylcyclotetrasiloxane [541-02-6], Melamine [108-78-1], Octamethylcyclotetrasiloxane [556-67-2], Dodecamethylcyclohexasiloxane [540-97-6], C,C'-azodi(formamide) [123-77-3], TBBA [79-94-7], Cobalt(II) nitrate hexahydrate [10026-22-9], N,N-Dimethylacetamide [127-19-5], Tris(nonylphenyl)phosphite [26523-78-4]
Power Transmission - [front axle / rear axle / drive shaft]	AOC, REAR AXLE, FEEDER PUMP KIT, BRACKET, FINAL DRIVE, PUMP UNIT, BEARING ANCHORAGE, FLANGE SCREW	Lead [7439-92-1], Melamine [108-78-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclotetrasiloxane [541-02-6], Cobalt-dichloride [7646-79-9]
Electric Power Supply / Instruments - [lighting]	OVERHEAD CONSOLE LENS, LIGHTING, CONTROL UNIT HCM, HEADLAMP, REAR LAMP, READING LAMP, LAMP LED, FOG LIGHT, MODULE, LED MODULE	Lead [7439-92-1], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Dicyclohexyl-phthalate [84-61-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 1-Methyl-2-pyrrolidone [872-50-4], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Octamethylcyclotetrasiloxane [556-67-2], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1]

Engine - [cooling system]	WATER PUMP, ELECTRIC WATER PUMP, HOSE, HOSE RADIATOR QC, FAN, VALVE, TWO-WAY VALVE, THREE-WAY VALVE, HOSE OUTLET, HOSE MODULE, PIPE, COOLING MODULE, RETURN PIPE, CONDENSER, PUMP, 4WAY VALVE, TEMPERATURE SENSOR, BRACKET, CLAMP BRACKET, HOSE OBC, COOLER, SET, THERMOSTAT HOUSING, O-RING, NIPPLE, PLASTIC PIPE, GASKET, INLET PIPE, COVER, SIX POINT SOCKET SCREW, MODULE WATER PUMP, BRACKET TEMP SENSOR, STRIKER PLATE	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], TBBA [79-94-7], Melamine [108-78-1], Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Silicic acid, lead salt [11120-22-2], 1-Methyl-2-pyrrolidone [872-50-4], 4,4'-Isopropylidenediphenol [80-05-7], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead(II,IV)-oxide [1314-41-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [instrument / radio panel]	DECOR DIAMOND CUT, DECOR WOOD, LIGHTNING INSTRUMENT PANEL, PANEL NOZZLE, INSTRUMENT PANEL, FRAME, HINGE PIN, GLOVE BOX, DECOR SPINNAKER, LED MODULE, DIM COOLING	TBBA [79-94-7], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], C,C'-azodi(formamide) [123-77-3]
Electric Power Supply / Instruments - [electric drive system]	ONBOARD CHARGER, INVERTER TRANSDUCER, INVERTER, VOLTAGE CONVERTER, STARTER MOTOR ALTERNATOR, BRACKET, FUSE, COOLANT PIPE, SENSOR, STARTER MOTOR, FLANGE SCREW	4,4'-Isopropylidenediphenol [80-05-7], 2-Methylimidazole [693-98-1], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Dodecamethylcyclohexasiloxane [540-97-6], Terphenyl, hydrogenated [61788-32-7], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 4-Nonylphenol, branched [84852-15-3], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Alkanes, C14-17, chloro [85535-85-9], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Dicyclohexyl-phthalate [84-61-7], N,N-Dimethylacetamide [127-19-5], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Cobalt-dichloride [7646-79-9]
Electric Power Supply / Instruments - [infotainment system]	DISPLAY, CONTROL UNIT, USB HUB, PRINTED CIRCUIT BOARD, TV TUNER	Boric acid [10043-35-3], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3]
Engine - [control systems]	CONTROL UNIT, AIR TEMP SENSOR, MASS AIR FLOW SENSOR, TEMP AND PRESSURE SENSOR, PRESSURE SENSOR	Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Dicyclohexyl-phthalate [84-61-7], Lead titanium zirconium oxide [12626-81-2]
Electric Power Supply / Instruments - [cleaner]	WASHER FLUID RESERVOIR, REAR WIPER, WIPER APPARATUS, WIPER ARM, PUMP, WASHER PUMP	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Imidazolidine-2-thione [96-45-7]

Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, ACTUATOR, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead [7439-92-1], Lead-monoxide [1317-36-8], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [battery and mounting parts]	BMS, BATTERY, BATTERY MODULE, CURRENT SENSOR, BATTERY CONTROL UNIT, CELL VOLTAGE TEMP NODE, BATTERY DISCONNECT UNIT, CONTROL UNIT, SLAVE, HOUSING, PLUG, BUSBAR, RAIL INLET, RAIL, 48V BATTERY, SERVICE LID, SWITCH, FLANGE NUT, SOCKET, TEMPERATURE SENSOR, HOLDER, SUPER CAPACITOR, MAIN RELAY	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Barium-diboron-tetraoxide [13701-59-2], Lead titanium zirconium oxide [12626-81-2], Cobalt chloride [7791-13-1], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Bis(2-ethylhexyl) tetrabromophthalate [26040-51-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1,3-Propanesultone [1120-71-4], Alkanes, C14-17, chloro [85535-85-9], Melamine [108-78-1], Dodecamethylcyclohexasiloxane [540-97-6], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Cobalt-dinitrate [10141-05-6], Tris(2-methoxyethoxy)vinylsilane [1067-53-4], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
Electric Power Supply / Instruments - [vehicle control system]	ECU, COMBI INSTRUMENT, CONTROL UNIT DOOR, LOCK BUTTON, BUTTON, ECU MODULE SEAT HEATING, SWITCH DOOR, HARDWARE, SWITCH, CONTROL PANEL 12W, SWITCH PANEL, STALK MODULE, SWITCH CRUISE CONTROL, CUT-OFF SWITCH, USB POWER OUTLET, SWITCH WINDOW LIFT	Lead titanium zirconium oxide [12626-81-2], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Boric acid [10043-35-3], 4,4'-Isopropylidenediphenol [80-05-7], Lead-titanium-trioxide [12060-00-3]
Engine - [fuel / EVAP system]	PURGE LINE ASSY, FUEL LINE ASSY, PURGE LINE, EVAP PURGE PUMP, PURGE VALVE, LEAK DETECTION PUMP, ISOLATION VALVE, FUEL PRESSURE SENSOR, CANISTER, PEM, BRACKET, FOAM PAD, FUEL TANK, FUEL LEVEL SENSOR, FUEL PUMP, VENTILATION LINE, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, INJECTOR, DELIVERY PIPE, INJECTION VALVE	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Melamine [108-78-1], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], C,C'-azodi(formamide) [123-77-3], Boric acid [10043-35-3]
Electric Power Supply / Instruments - [cable system high voltage]	CABLE CHARGE POINT HV, CABLE HARNESS ENGINE, CHARGE CABLE CORD, CHARGE CABLE, CABLE HARNESS, BRACKET, CABLE HARNESS HV, CABLE HARNESS IEM DC, STRAIN RELIEF, CABLE DUCT, CHANNEL, CABLE HV, ADAPTER PLATE	Lead-monoxide [1317-36-8], Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Melamine [108-78-1], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]

Wheel Suspension / Steering [steering gear / wheel / shaft / column]	STEERING WHEEL, STEERING GEAR, STEERING COLUMN LOCK, STEERING COLUMN MANUAL	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], 4,4'-Isopropylidenediphenol [80-05-7]
Body, Interior / Exterior - [recovery / towing unit]	HARNESS, TOWING HOOK, TRM	Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7]
Brake - [master cylinder / brake booster]	ACTUATION UNIT, LEVEL SENSOR, SHELL	Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8]
Electric Power Supply / Instruments - [antenna]	BLUETOOTH ANTENNA, ANTENNA AMPLIFIER, MAM ANTENNA MODULE, WAVE TRAP, GROUND SIDE COIL, ANTENNA, ETC ON BOARD UNIT, ETC MODULE	Lead [7439-92-1], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 4,4'-Isopropylidenediphenol [80-05-7], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1-Propanol, 2,3-dibromo- [96-13-9]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT MKC1, HYDRAULIC UNIT, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Body, Interior / Exterior - [tool / jack]	COMPRESSOR, JACK	Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], Ethylenediamine [107-15-3]
Body, Interior / Exterior - [instruction / information plates]	NUMBER PLATE HOLDER, DECAL SRS	Lead [7439-92-1], 2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], Imidazolidine-2-thione [96-45-7]
Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR, CAMERA, REAR VIEW MIRROR OUTER, MOTOR UNIT, GLASS	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], Dicyclohexyl-phthalate [84-61-7], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt-dinitrate [10141-05-6]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	CARRIER, WELD SEALANT CURING, ADHESIVE, WELD NUT	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Boric acid [10043-35-3]

Engine - [intercooler / connection]	CHARGE AIR PIPE	Lead [7439-92-1]
Power Transmission - [electrical axis drive]	FRONT AXLE, REAR AXLE, INNER HOUSING, OUTER HOUSING, BRACKET, ELECTRIC MOTOR, O-RING, INVERTER, FLANGE SCREW, TRANSMISSION HOUSE, PLUG, PLANET CARRIER	Lead [7439-92-1], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Power Transmission - [gearbox]	TORQUE CONVERTER, COOLING PIPE, GEARBOX, SPACER, ELECTRIC MOTOR, CONTROL UNIT, VALVE BODY, CABLE HARNESS, CONNECTOR, AUTOMATIC GEARBOX, SERVO COVER, CONTROL SYSTEM, OIL PUMP, PLUG, NEUTRAL POSITION SENSOR, CONTROL HOUSING, TEMPERATURE SENSOR, INJECTOR PIPE, VALVE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Dioctyltin dilaurate [3648-18-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Nonylphenol [25154-52-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], N,N-Dimethylacetamide [127-19-5], Lead-titanium-trioxide [12060-00-3], 2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], 2-Methylimidazole [693-98-1]
Electric Power Supply / Instruments - [automatic monitoring / control]	SENSOR, CONTROL UNIT, RAIN SENSOR, REMOTE KEY, TRM, SIREN, PRINTED CIRCUIT BOARD	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 4,4'-Isopropylidenediphenol [80-05-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead(II,IV)-oxide [1314-41-6], TBBA [79-94-7]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE REAR, BRAKE PIPE ENGINE COMPART, BRAKE PIPE FRONT, BRAKE HOSE REAR	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [outside / exterior trim]	GRILLE, RAILS, MOULDING	C,C'-azodi(formamide) [123-77-3], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Engine - [emission equipment]	LAMBDA SOND, ALUMINIUM, STAY, PRESSURE SENSOR, FLANGE SCREW, VALVE	Diboron-trioxide [1303-86-2], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Cobalt-dichloride [7646-79-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Body, Interior / Exterior - [trunk lid / tailgate complete]	TAILGATE, SPINDLE DRIVE, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]

Brake - [wheel brake]	BRAKE LINING, BRAKE CALIPER, HOUSING, AIR VENTING NIPPLE, EPB, BLEEDER VALVE, MOTOR UNIT, DUST COVER	Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1], Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], Hexahydromethylphthalic-anhydride [25550-51-0]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methylimidazole [693-98-1], Melamine [108-78-1]
Engine - [engine / engine mounting]	BRACKET ENGINE MOUNT, ENGINE MOUNT, BRACKET, TORQUE ROD, GEARBOX ATTACHMENT, TORQUE LINK BRACKET, FRONT AXLE, ELECTRIC MOTOR, REAR AXLE, INNER HOUSING, OUTER HOUSING, O-RING, STRAIN RELIEF, CABLE HARNESS	Lead [7439-92-1], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], Decamethylcyclotetrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, WIRELESS CHARGE SYSTEM, BATTERY, RETAINER, ANTENNA, BACK-UP BATTERY, AUXILIARY TELEMATIC, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methylimidazole [693-98-1], N,N-Dimethylacetamide [127-19-5], Dioctyltin dilaurate [3648-18-8]
Power Transmission - [clutch control]	CONNECTION PIPE	Cobalt(II) nitrate hexahydrate [10026-22-9]
Body, Interior / Exterior - [interior equipment]	ARM REST, EC REAR VIEW MIRROR, DAWN, AIR OUTLET, BRACKET, CUP HOLDER, REAR BRACKET	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4]
Power Transmission - [final drive]	PT-UNIT, BRACKET	Lead [7439-92-1]
Brake - [brake control]	MASTER CYLINDER, BRAKE LIGHT SWITCH, CLUTCH PEDAL, SENSOR	Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [seat belt / other restraining systems]	HEIGHT ADJUSTMENT, BELT, BELT CATCH, SEAT BELT	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead-monoxide [1317-36-8]
Body, Interior / Exterior - [exterior equipment]	SPOILER, STOP LAMP, EXT743	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], 2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], 4,4'-Isopropylidenediphenol [80-05-7]

Engine - [fan]	FAN	Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], 2-Methylimidazole [693-98-1], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [electric drive system, high voltage]	CELL VOLTAGE TEMP NODE, BATTERY CONTROL UNIT	Diboron-trioxide [1303-86-2], Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Lead-monoxide [1317-36-8]
Body, Interior / Exterior - [roof]	PANORAMA ROOF, FRAME, ADHESIVE ROOF HATCH, ADHESIVE, ROOF, GLASS PANEL, MOTOR	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], C,C'-azodi(formamide) [123-77-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Frame / Springs / Damping / Wheels - [rim]	ADHESIVE BALANCE WEIGHT, KEY, WHEEL BOLT	Diboron-trioxide [1303-86-2], Lead [7439-92-1], 2-Methylimidazole [693-98-1]
Wheel Suspension / Steering - [axle member / link arm / suspension]	BUSHING, SUBFRAME REAR	Lead [7439-92-1]
Body, Interior / Exterior - [airbag]	CONTROL UNIT SRS, CONTROL UNIT, AIRBAG, AIRBAG MODULE	Lead-monoxide [1317-36-8], Lead [7439-92-1], Refractory ceramic fibres [142844-00-6], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, QUARTER GLASS DOOR HARDENED, REAR SCREEN, GLASS HARDENED	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [hood cover]	HOOD, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION, SEALANT REPAIR, SOUND INSULATION	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [body side]	ADHESIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [alternator]	REGULATOR LIN, ALTERNATOR 210A, ALTERNATOR	Lead [7439-92-1], TBBA [79-94-7]
Electric Power Supply / Instruments - [starting system]	STARTER MOTOR	Lead [7439-92-1], Ethylenediamine [107-15-3], Refractory ceramic fibres [142844-00-6], Diboron-trioxide [1303-86-2]



Engine - [miscellaneous / help device installation]	TENSIONER, SPLASH PROTECTION, BRACKET, TENSIONING ARM, GUIDE SLEEVE	Lead [7439-92-1]
Body, Interior / Exterior - [tank hatch]	PLASTIC MODULE	Lead [7439-92-1]
Power Transmission - [actuator, gear shift]	CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Silicic acid, lead salt [11120-22-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK ANTI-ROLL BAR	Imidazolidine-2-thione [96-45-7]
Electric Power Supply / Instruments - [protection]	SENSOR	Lead [7439-92-1], Lead-monoxide [1317-36-8]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	COVER	Lead [7439-92-1]
Electric Power Supply / Instruments - [horn]	HORN	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [climate unit]	CONTROL UNIT	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2]
Engine - [accelerator control]	ACCELERATOR PEDAL	Lead [7439-92-1], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9]
Engine - [supercharging]	SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, O-RING, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, MP TURBO, INLET PIPE	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-monoxide [1317-36-8], Dicyclohexyl-phthalate [84-61-7]
Engine - [transmission]	TENSIONER, CAMSHAFT, IDLER PULLEY, HOUSING, SOLENOID, GASKET, BALANCE SHAFT, BELT PROTECTOR, BELT COVER, VVT ACTUATOR, SLEEVE	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [lubricating and oil system]	OIL SUMP, SUCTION LINE, OIL PUMP, PISTON COOLING JET, GASKET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, OIL FILTER, PLUG, OIL PRESSURE SENSOR	Lead [7439-92-1], Bis(4-chlorophenyl) sulfon [80-07-9], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2]

Engine - [cylinder block / head]	CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [distributor]	CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]
Engine - [ignition / spark plug]	GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Engine - [air cleaner]	RESONATOR, HOSE MODULE	Lead [7439-92-1]